

ASS. REC. BY:

REF:

C12 / 220047391ke

C

Henneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ Wei Lee

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PMN 89107 Yr Regn: 12, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 300842 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RAU1-1102775Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD / R/Rim orTyre Size: F: Westlake 215/60R16R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 15/5/22

Survey held at

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 18/5/2022Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1915 21 Sep @ 1200 Contin

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# 威利摩多 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

17, May 2022

China Taiping Insurance (S) PL  
105 Cecil Street  
#18-00 The Octagon  
S 069534

Attn: Motor claim dept-3<sup>rd</sup> party claim

Accident involving vehicle no: SMN8910T/SLK7310J

Claiming against your insured vehicle no: SLK7310J

DOA: 15/05/2022 AT 359A Tampines Street 34 MSCP at the carpark gantry

Dear officer incharge

Estimate cost of repair for vehicle no: SMN8910T

To Supply--

| Description                        | Qty | Amount   |
|------------------------------------|-----|----------|
| Front bumper <i>762.70</i>         | 1   | 891.10   |
| Front grille base <i>CM</i>        | 1   | 301.20   |
| Front grille garnish <i>not in</i> | 1   | 203.40   |
| Front headlamp lower bracket       | 1   | 53.70    |
| Front grille chrome @68.50         | 2   | 137.00   |
| Parts                              |     | 1,586.10 |
| Parts less 20%                     |     | 317.22   |
|                                    |     | 1,268.88 |

To remove damaged parts and attachments

To repair/reshape damaged areas

Replace/align all parts into position

To spray paint

650.00

550.00

2,468.88

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Surveyor - Kenneth*  
*18/5/22 - AM*  
*Not Authorized*  
*11 Pm @ 1200h*  
*Planned After Rain*  
*2 days*