

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** SVY210100073  
**Date:** 18/01/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MSBS0077/02
<b>Claimant Vehicle No :</b>	SGC4844G	<b>Insured Vehicle No :</b>	SG1235X
Date of Loss:	16/03/2019	Nature of Claim:	TP
		Claim No:	MCS20184567

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGC4844G</b>		
Make & Model:	LEXUS GS300, 3.0 (A)	Engine No:	3GR0129870
Reg. Date:	18/01/2006 (Man. Year: 2006)	Chassis No:	JTHBG96S005022633
Colour:	Black	Odometer:	126154 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,105.28	3,672.15	4,433.13	54.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,390.00	1,590.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,085.28</b>	<b>5,062.15</b>	<b>6,023.13</b>	<b>54.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		
<b>(S\$)</b>	11,085.28	4,050.00	7,035.28	63.47
<b>+ GST 7.00/7.00% (S\$)</b>	775.97	283.50	492.47	63.47
<b>Nett Amount (S\$)</b>	<b>11,861.25</b>	<b>4,333.50</b>	<b>7,527.75</b>	<b>63.47</b>

### INSPECTION

Date of Assignment:	15/01/2021	
Date Inspected:	18/01/2021	Inspected At:
Estimated Period of Repair:	5.0 days	

**Adjuster:** Tay Beng Hee

**Manager:** Tay Beng Hee

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**VALUATION (COE EXPIRY ON 17/01/2026)**

Market Value:\$50,000.00

LTA Rebate :\$40,022.00 (as at 19/03/2019)

Net Value :\$ 9,978.00

**INSPECTIONS**

Pre-repair inspection conducted on 19/03/2019.

Dismantled parts inspection conducted on 20/03/2019.

Post-repair inspection conducted on 26/03/2019.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2021)
<b>Parts:</b> 143	LEXUS GS300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> AutoProbe Consultants/SGC4844G/18/01/2021 14:36	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Boot lid	Dented	961.90 FL	*961.90 FL
2	1		*Boot lid centre garnish	Mtg Cracked	361.40 FL	*361.40 FL
3	1		*Boot lid emblem	Necessary	83.40 FL	*83.40 FL
4	1		*Boot lid Lexus plate	Necessary	82.70 FL	*82.70 FL
5	1		*Boot lid GS300 plate	Necessary	82.70 FL	*82.70 FL
6	1		*Boot lid inner lock assy	Reuse	1,236.40 FL	*- FL
7	1		*Boot lid inner lock catch	Serviceable	76.10 FL	*- FL
8	2		*Boot lid hinges	Serviceable	191.20 FL	*- FL
9	2		*Boot lid dampers	Serviceable	543.60 FL	*- FL
10	2		*Boot lid reflectors	RH Reuse	592.20 FL	*296.10 FL
11	1		*Boot rubber	Serviceable	195.90 FL	*- FL
12	2		*Rear lamps assy	Reuse	1,566.52 FL	*- FL
13	1		*Rear panel	Repair	642.10 FL	*- FL
14	1		*Rear bumper fascia	Deformed	864.90 FL	*864.90 FL
15	1		*Rear bumper inner sponge	Cracked	135.70 FL	*135.70 FL
16	1		*Rear bumper reinforcement	Dented	578.50 FL	*578.50 FL
17	2		*Rear bumper side retainers	Necessary	117.80 FL	*117.80 FL
18	1		*Rear no plate lamps assy	Affected	168.40 FL	*168.40 FL
19	1		*Boot lid centre garnish clips (set)	Necessary	28.00 FS	*28.00 FS
20	1		*Boot lid insulator clips (set)	Necessary	35.00 FS	*35.00 FS
21	1		*Rear end panel inner garnish clips (set)	Necessary	14.00 FS	*14.00 FS
22	1		*Rear end panel sealant	Not Necessary	60.00 FS	*- FS
23	1		*Rear bumper clips (set)	Necessary	35.00 FS	*35.00 FS
24	1		*Reverse sensors	Affected	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,953.42</b>	<b>4,045.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	848.14	373.35
<b>Total Parts (S\$)</b>	<b>8,105.28</b>	<b>3,672.15</b>

AutoProbe Consultants/SGC4844G/18/01/2021 14:36. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Remove boot lid fittings, check, renew damaged fittings, transfer all fittings to new boot lid assy and refit.	New	60.00	60.00
2	Remove necessary interior upholstery and fittings to enable necessary repairs, check and refit same.	New	80.00	40.00
3	Remove lamps, necessary wiring and electrical fittings to enable necessary repairs, check, replace damaged parts, refit same, test electrical-circuit.	New	30.00	30.00
4	Renew reverse sensors, transfer same to new bumper assy, refit, reset and test system.	New	80.00	50.00
5	Remove rear exhaust pipe assy, repair and refit same.	New	180.00	0.00
6	Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary.	New	1,000.00	500.00
7	Paint replacement parts and repaint damaged sections with welded portions in and outside.	New	1,400.00	650.00
8	Rust proof replacement parts and touch up damaged sections.	New	150.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,980.00</b>
				<b>1,390.00</b>

AutoProbe Consultants/SGC4844G/18/01/2021 14:36. Not valid without Reference section.

< END OF ESTIMATES >