

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004744/KPA3Q2**Date:** 27/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100411260
Claimant Vehicle No :	SHD126E	Insured Vehicle No :	SKT2289K
Date of Loss:	15/05/2022	Nature of Claim:	TP
		Claim No:	6624827156SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD126E		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003183
Reg. Date:	31/08/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283335
Colour:	Metallic White/Red	Odometer:	428345 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,647.84	4,627.70	5,020.14	52.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	1,520.00	6,360.00	80.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,527.84	6,147.70	11,380.14	64.93
Approved Total (Overridden) (\$\$)		4,900.00		
(\$\$)	17,527.84	4,900.00	12,627.84	72.04
+ GST 7.00/7.00% (\$\$)	1,226.95	343.00	883.95	72.04
Nett Amount (\$\$)	18,754.79	5,243.00	13,511.79	72.04
+ Loss of Use (8.0 x \$50.00/day) (\$\$)		400.00		
+ Car Rental (8.0 x \$97.37/day) (\$\$)		778.96		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,429.41		

INSPECTION

Date of Assignment:	18/05/2022		
Date Inspected:	18/05/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Buckled	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
12	1		*OUTER PANEL REAR (END PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
13	1		*SPARE WHEEL PANEL	Repair	1,229.40 FL	*- FL
14	1		*BOOT REAR	Buckled	1,677.20 FL	*1,677.20 FL
15	1		*BOOT LOCK	Repair	246.60 FL	*- FL
16	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
19	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
20	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
21	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
22	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
23	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
24	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
25	1		*TAILLAMP RH	Mtg Cracked	401.40 FL	*401.40 FL
26	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
27	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
29	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
30	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
31	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
32	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
33	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
34	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
35	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
36	1		*REAR BUMPER ADVERTISEMENT	Not Necessary	100.00 FS	*- FS
37	1		*LICENSE PLATE WITH HOLDER REAR	Serviceable	120.00 FS	*- FS
38	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
39	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
40	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,525.16	5,120.56
- List Item Discount on L Items 10.00/10.00% (\$\$)	877.32	492.86
Total Parts (\$\$)	9,647.84	4,627.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	600.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			7,880.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >