

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22004746/AQCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	KALUSKAR PRAJAKTA SUBODH	Policy No:	7210077579	
Date of Loss:	13/05/2022	Nature of Claim:	OD	Claim No: 3247894881SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMU751B</b>		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC40998
Reg. Date:	26/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF33M1124165
Colour:	Grey	Odometer:	19721 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,250.00	9,195.84	24,054.16	72.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,372.00	5,602.00	5,770.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,622.00</b>	<b>14,797.84</b>	<b>29,824.16</b>	<b>66.84</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	44,222.00	14,397.84	29,824.16	67.44
<b>+ GST 7.00/7.00% (S\$)</b>	3,095.54	1,007.85	2,087.69	67.44
<b>Nett Amount (S\$)</b>	<b>47,317.54</b>	<b>15,405.69</b>	<b>31,911.85</b>	<b>67.44</b>

**INSPECTION**

Date of Assignment:	20/05/2022	
Date Inspected:	19/05/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	3,008.00 FS	*2,406.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	433.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT UPPER - LH / RH	Not Necessary	132.00 FS	*- FS
4	1		*FRONT BUMPER TRIM - CENTER	Deformed	396.00 FS	*316.40 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Deformed	242.00 FS	*193.60 FS
6	2		*FRONT BUMPER GRILLE ULTRA SENSOR SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
7	1		*FRONT BUMPER COVER LOWER - CENTER	Cut	58.00 FS	*45.68 FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	212.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Deformed	850.00 FS	*679.60 FS
10	1		*FRONT BUMPER BRACKET	Not Necessary	24.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE TRIM - LH / RH	Not Necessary	364.00 FS	*- FS
13	2		*FRONT AIR GUIDE GRILLE ULTRA SENSOR SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	2,135.00 FS	*1,708.00 FS
15	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
16	1		*RADIATOR GRILLE COVER CAP	Not Necessary	256.00 FS	*- FS
17	1		*RADIATOR GRILLE BRACKET	Not Necessary	46.00 FS	*- FS
18	1		*RADIATOR GRILLE COVER CAP	Cracked	271.00 FS	*216.80 FS
19	1		*FRONT CAMERA	Not Necessary	1,261.00 FS	*- FS
20	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	974.00 FS	*778.80 FS
21	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	114.00 FS	*91.20 FS
22	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
23	1		*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
24	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
25	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
26	4		*FRONT PARKING AID SENSOR	Not Necessary	1,060.00 FS	*- FS
27	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*SET FRONT BUMPER WIRING	Snapped	637.00 FS	*509.60 FS
29	2		*HORN - LH / RH	Not Necessary	298.00 FS	*- FS
30	2		*HORN SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
31	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	264.00 FS	*210.40 FS
32	2		*HEADLIGHT - LH / RH	Not Necessary	11,904.00 FS	*- FS
33	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
34	1		*LIFT CYLINDER HOSE	Cut	92.00 FS	*73.44 FS
35	1		*LOCK CARRIER	Not Necessary	1,412.00 FS	*- FS
36	1		*A/C CONDENSER	Dented	605.00 FS	*483.60 FS
37	1		*TEMPERATURE SENSOR HOLDER	Damaged	9.00 FS	*6.48 FS
38	1		*ADDITIONAL RADIATOR	Not Necessary	982.00 FS	*- FS
39	1		*RADIATOR	Not Necessary	1,090.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE - UPPER / LOWER	Lower Damaged	96.00 FS	*37.84 FS
41	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
42	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Cracked	86.00 FS	*68.16 FS
43	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	520.00 FS	*- FS
44	2		*FRONT WHEEL HOUSING LINER COVER - LH / RH	Not Necessary	36.00 FS	*- FS
45	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
46	1		*FRONT NO PLATE	Dented	120.00 FS	*120.00 FS
47	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 33,250.00 9,195.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,700.00	480.00
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	2,000.00
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	1,250.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,372.00</b>	<b>5,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >