

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004747/AVCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	JIMYONG PTE LTD	Policy No:	7210082161	
Date of Loss:	13/05/2022	Nature of Claim:	OD	Claim No: 7933387880SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB1509S		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM033421
Reg. Date:	30/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF40MA080425
Colour:	Grey	Odometer:	18311 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,652.00	11,367.60	5,284.40	31.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,202.00	3,302.00	1,900.00	36.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,854.00	14,669.60	7,184.40	32.87
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	21,304.00	14,119.60	7,184.40	33.72
+ GST 7.00/7.00% (S\$)	1,491.28	988.37	502.91	33.72
Nett Amount (S\$)	22,795.28	15,107.97	7,687.31	33.72

INSPECTION

Date of Assignment:	20/05/2022		
Date Inspected:	19/05/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	293.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	51.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT-UPPER CENTER	Cracked	293.00 FS	*234.00 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Damaged	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER TRIM-LH	Not Necessary	54.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	212.00 FS	*169.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
15	1		*AIR CON STICKER	Not Necessary	9.00 FS	*- FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
17	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	64.00 FS	*- FS
18	4		*FRONT BUMPER POP RIVET	Necessary	4.00 FS	*2.88 FS
19	1		*FRONT PARKING AID SENSOR-INNER (NPA)	Not Necessary	0.00 FS	*- FS
20	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*HORN-LH	Not Necessary	134.00 FS	*- FS
22	1		*HORN SUPPORT-LH	Not Necessary	33.00 FS	*- FS
23	1		*HEADLIGHT-LH	Cut	8,172.00 FS	*6,537.60 FS
24	1		*LIFT CYLINDER-LH	Not Necessary	231.00 FS	*- FS
25	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
26	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
27	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE OUTER-LH	Not Necessary	51.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE INNER-LH/RH	Not Necessary	38.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	19.00 FS	*- FS
31	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Necessary	350.00 FS	*16.32 FS
33	1		*FRONT REINFORCEMENT BEAM BRACKET-LH (Supplementary)	Bent	254.00 FS	*203.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	16,652.00	11,367.60
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.TO REPAIR BONNET.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISLOSGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF LHS FRONT REINFORCEMENT BEAM BRACKET. (Supplementary)	New	780.00	780.00
Gross Labour Cost (\$\$)			5,202.00	3,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >