

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22004748/UPA3Q2**Date:** 08/08/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0004095_01

Claimant Vehicle No : GBH2236H **Insured Vehicle No :** YP2418K

Date of Loss: 19/05/2022 Nature of Claim: TP Claim No: MCV2022D0002603

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH2236H**

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KD2773331

Reg. Date: 13/03/2018 (Man. Year: 2017)

Chassis No: KDY2318032162

Colour: Silver

Odometer: 111948 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R13 (D)

Front Left Side: KAPSEN 6 mm

Rear Left Side: Goform 6/6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: Goform 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,282.70	7,725.20	16,557.50	68.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	4,160.00	3,490.00	45.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,932.70	11,885.20	20,047.50	62.78
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	31,932.70	9,500.00	22,432.70	70.25
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
Nett Liability (S\$)		10,140.00		
Global Sum Settlement (S\$)		10,100.00		

INSPECTION

Date of Assignment: 20/05/2022

Date Inspected: 20/05/2022 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2236H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,860.00 F	*1,482.50 FL
2	1		*REAR TAILGATE LOCK LATCHS	N/S Not Necessary / O/S Bent	760.00 F	*181.20 FL
3	1		*REAR TAILGATE LOCK LOWER L BRACKETS	N/S Not Necessary / O/S Bent	360.00 F	*110.50 FL
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Serviceable	240.00 F	*- FL
5	1		*REAR TAILGATE DYNA STICKER	Necessary	80.00 F	*58.60 FL
6	1		*REAR TAILGATE TOYOTA STICKER	Necessary	281.00 F	*180.60 FL
7	1		*TAILLAMPS	N/S Not Necessary / O/SCracked	900.00 F	*295.20 FL
8	1		*TAILLAMP HOUSING PANELS	N/S Not Necessary / O/S Bent	360.00 F	*165.10 FL
9	1		*REAR LICENCE PLATE BRACKET	Not Necessary	345.00 F	*- FL
10	1		*REAR EXHAUST	Not Necessary	1,250.00 F	*- FL
11	1		*REAR EXHAUST MOUNTING	Not Necessary	85.00 F	*- FL
12	1		*REAR END PANEL	Bent	685.10 F	*685.10 FL
13	1		*REAR SPARE TYRE CARRIER & CHAIN	Not Necessary	680.00 F	*- FL
14	1		*DROPSIDE GATE PANEL O/S	Repair	2,290.00 F	*- FL
15	1		*TAILGATE REFLECTOR O/S	Not Necessary	118.00 F	*- FL
16	1		*FRONT WINDSCREEN	Not Necessary	1,465.10 F	*- FL
17	1		*FRONT WINDSCREEN RUBBER	Necessary	399.20 F	*305.10 FL
18	1		*WIPER PANEL GARNISH	Dented	871.10 F	*681.20 FL
19	1		*WIPER MOTOR	Non original	665.00 F	*- FL
20	1		*WIPER ARM O/S	Serviceable	231.80 F	*- FL
21	1		*FRONT PANEL	Badly Dented	1,865.20 F	*1,451.20 FL
22	1		*FRONT PANEL DYNA STICKER	Not Necessary	95.00 F	*- FL
23	1		*FRONT GRILLE	Cracked	1,145.20 F	*1,026.10 FL
24	1		*FRONT GRILLE LOGO	Necessary	105.00 F	*70.40 FL
25	1		*HEADLAMP O/S	Cracked	1,545.80 F	*1,095.20 FL
26	1		*FRONT CORNER PANEL GARNISH O/S	Cracked	655.10 F	*341.20 FL
27	1		*FRONT DOOR O/S	Repair	1,855.10 F	*- FL
28	1		*FRONT DOOR OUTER PILLAR O/S	Dented / Bent	899.20 F	*899.20 FL
29	1		*FRONT BUMPER	Warped / Torn	845.20 F	*683.90 FL
30	1		*FRONT BUMPER BRACKET O/S	Bent	295.50 F	*211.20 FL
31	1		*FRONT FOG LAMP O/S	Cracked	450.10 F	*350.10 FL
32	1		*SET REAR TAILGATE 70KM/H & 13 PAX STICKER	Necessary	50.00 FS	*20.00 FS
33	1		*SET REAR REVERSE SENSOR	Not fitted	300.00 FS	*- FS
34	1		*REAR LICENCE PLATE	Serviceable	50.00 FS	*- FS
35	1		*REAR STEP BRACKET	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 24,282.70 10,293.60
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 2,568.40

Total Parts (\$\$) 24,282.70 7,725.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	0.00
3	TO DISMANTLE & REPLACED REAR CARGO DECK	New	800.00	480.00
4	TO STRAIGHTEN & REALIGN CHASSIS	New	1,000.00	0.00
5	TO DISMANTLE & REFIX DASHBOARD	New	380.00	250.00
6	TO SPRAY RUST PROOFING	New	200.00	100.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,500.00	1,600.00
8	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,600.00
9	TO REFILL AIR CON GAS	New	120.00	100.00
Gross Labour Cost (S\$)			7,650.00	4,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >