

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22004750/ANY3Q2**Date:** 30/11/2022REFERENCE

Insured/Claimant:	JOEL GAY	Policy No:	MP320159		
Date of Loss:	14/05/2022	Nature of Claim:	OD	Claim No:	MPC03411/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2244E		
Make & Model:	AUDI A4, 1.4 (A)	Engine No:	CVN018177
Reg. Date:	30/11/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF44HA031797
Colour:	Red	Odometer:	89198 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,412.00	8,444.50	5,967.50	41.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,283.70	2,273.70	2,010.00	46.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,695.70	10,718.20	7,977.50	42.67
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,095.70	10,118.20	7,977.50	44.09
+ GST 7.00/7.00% (S\$)	1,266.70	708.27	558.43	44.09
Nett Amount (S\$)	19,362.40	10,826.47	8,535.93	44.09

INSPECTION

Date of Assignment:	20/05/2022		
Date Inspected:	20/05/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2022)
Parts:	143	AUDI A4 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ2244E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	254.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Cut	151.00 FS	*150.50 FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
11	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
12	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
13	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	64.00 FS	*- FS
15	4		*FRONT BUMPER POP RIVET	Not Necessary	4.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	262.00 FS	*- FS
17	1		*FRONT WHEEL SPOILER -RH	Not Necessary	82.00 FS	*- FS
18	1		*HEADLIGHT -RH	Cut	8,294.00 FS	*8,294.00 FS
19	1		*LIFT CYLINDER -RH	Not Necessary	231.00 FS	*- FS
20	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
21	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
22	1		*RADIATOR AIR GUIDE OUTER-RH	Not Necessary	32.00 FS	*- FS
23	1		*RADIATOR AIR GUIDE INNER-RH	Not Necessary	14.00 FS	*- FS
24	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	19.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
					Total Parts (S\$)	14,412.00 8,444.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TOWING FROM ACCIDENT SCENES BY OWNER	New	160.50	160.50
7	TOWING FROM UBI TO REPORTING CENTRE (2 TRIP) BY OWNER	New	171.20	171.20
Gross Labour Cost (\$\$)			4,283.70	2,273.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >