

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22004751/Eqce2	
	8 SHENTON WAY SINGAPORE 0688		Date:	27/05/2022		
	ATTN: ANG YVON	NE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFW 1880C	Veh. Inspected		FBR 5865U	
	Policy No.	GA448814	Coverage (\$)		0.00	
	Claim No.	S2M040ZL	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		20/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA AEROX	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG4640LJ067574	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90-14	BRIDGESTONE		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/90-14	BRIDGESTONE		4 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5.	5. General Information					
	Accident Date	06/05/2022	Inspect Date / 1	Гіте	20/05/2022 (02:42 PM)	
	Survey held at	34 TOH GUAN ROAD EAST #01	-29 SINGAPORE 6	608579		
	Repairer	M 1 MOTORING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22004751/Eqce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser