

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004753/UVY3M4**Date:** 31/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00171492100

**Claimant Vehicle No :** SBM7878X **Insured Vehicle No :** SNB4211E

Date of Loss: 18/05/2022 Nature of Claim: TP Claim No: SNM22D203390/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SBM7878X**

Make & Model: TOYOTA MARK X, 2.5 (A) Engine No: 4GR0448841

Reg. Date: 11/09/2008 (Man. Year: 2008) Chassis No: GRX1203058730

Colour: Black Odometer: 177750 km

Engine Capacity: 2499 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/35ZR19 Rear Tyre Size: 235/35ZR19

Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,567.55	2,578.47	4,989.08	65.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	1,680.00	2,510.00	59.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,757.55</b>	<b>4,258.47</b>	<b>7,499.08</b>	<b>63.78</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (\$\$)</b>	<b>11,757.55</b>	<b>3,400.00</b>	<b>8,357.55</b>	<b>71.08</b>

**INSPECTION**

Date of Assignment: 19/05/2022

Date Inspected: 20/05/2022 Inspected At: Zoom Autowerks Pte Ltd (HQ)  
15 Kaki Bukit Road 4, #01-53  
Singapore 417808

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2022)
<b>Parts:</b>	143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBM7878X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	101.65 FL	*- FL
2	1		*REAR DOOR -RH	Repair	1,046.20 FL	*- FL
3	1		*REAR DOOR LOCK	Not Necessary	428.32 FL	*- FL
4	1		*REAR DOOR OUTER HANDLE	Not Necessary	60.13 FL	*- FL
5	1		*REAR DOOR REGULATOR	Not Necessary	185.96 FL	*- FL
6	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	646.79 FL	*- FL
7	1		*REAR DOOR RUBBER	Not Necessary	146.16 FL	*- FL
8	1		*ROCKER PANEL GARNISH RH	Cut / Torn	1,280.00 FL	*845.10 FL
9	1		*REAR BUMPER SIDE RETAINER	Not Necessary	64.70 FL	*- FL
10	1		*REAR FENDER -RH	Repair	1,230.50 FL	*- FL
11	1		*REAR FENDER AIR GATE	Not Necessary	114.40 FL	*- FL
12	1		*REAR FENDER INNER SHIELD	Not Necessary	82.55 FL	*- FL
13	1		*REAR WHEEL HUB WITH BEARING	Damaged	407.90 FL	*407.90 FL
14	1		*REAR SHOCK ABSORBER	Not Necessary	377.50 FL	*- FL
15	1		*REAR KNUCKLE ARM	Bent	849.60 FL	*849.60 FL
16	1		*REAR CONTROL ARM	Twisted	268.70 FL	*268.70 FL
17	1		*REAR LOWER ARM	Not Necessary	374.80 FL	*- FL
18	1		*REAR STAY ARM	Not Necessary	249.80 FL	*- FL
19	1		*REAR TOP ARM	Not Necessary	321.08 FL	*- FL
20	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*REAR BUMPER CLIP (1SET)	Not Necessary	60.00 FS	*- FS
22	1		*REAR TYRE	Serviceable	400.00 FS	*- FS
23	1		*REAR WHEEL RIM -RH	Bent / Warped	850.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,626.74</b>	<b>3,171.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,059.19	592.83
<b>Total Parts (\$)</b>	<b>7,567.55</b>	<b>2,578.47</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES.	New	150.00	80.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE.	New	350.00	120.00
4	TO CONDUCT WHEEL ALIGNMENT.	New	180.00	80.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	180.00	0.00
6	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	New	150.00	0.00
7	TO APPLY UNDERCOATING.	New	200.00	0.00
8	PANEL BEATING.	New	1,500.00	580.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.	New	1,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,190.00</b>	<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >