

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004754/UVY3N2**Date:** 07/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00108152104
Claimant Vehicle No :	SLS6519P	Insured Vehicle No :	GBC7948E
Date of Loss:	18/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203387/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6519P	Engine No:	PE10511443
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW1071H0125944
Reg. Date:	29/09/2017 (Man. Year: 2017)	Odometer:	89186 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,985.35	7,493.00	11,492.35	60.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	2,100.00	2,560.00	54.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,645.35	9,593.00	14,052.35	59.43
Approved Total (Overridden) (\$\$)		7,600.00		
Nett Amount (\$\$)	23,645.35	7,600.00	16,045.35	67.86

INSPECTION

Date of Assignment:	20/05/2022	15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807 REPAIRER: NINETEEN AUTOWERKS PTE. LTD
Date Inspected:	20/05/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS6519P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,871.10 FL	*1,637.00 FL
2	1		*TAILGATE LOGO	Necessary	99.00 FL	*85.00 FL
3	1		*TAILGATE EMBLEM MAZDA	Necessary	98.00 FL	*42.00 FL
4	1		*TAILGATE EMBLEM 5	Necessary	76.00 FL	*38.00 FL
5	1		*TAILGATE EMBLEM SKYACTIVE	Necessary	48.00 FL	*48.00 FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	295.00 FL	*162.60 FL
7	1		*TAILGATE INNER LOCK	Dented	475.00 FL	*286.90 FL
8	1		*TAILGATE LOCK SENSOR	Not Necessary	395.00 FL	*- FL
9	1		*TAILGATE OUTER GARNISH	Cracked	175.00 FL	*175.00 FL
10	1		*SET TAILGATE NUMBER PLATE LAMP	Not Necessary	210.00 FL	*- FL
11	2		*TAILGATE DAMPER	Not Necessary	390.00 FL	*- FL
12	1		*TAILGATE TRIMBOARD	Deformed/Cracked	452.00 FL	*421.60 FL
13	2		*TAILGATE REFLECTOR LAMP	Cracked	712.00 FL	*712.00 FL
14	2		*TAILLAMPS	Cracked	1,374.00 FL	*1,374.00 FL
15	1		*TAILGATE WINDSCREEN	Shattered	1,158.00 FL	*1,121.00 FL
16	1		*TAILGATE WINDSCREEN MOULDING	Necessary	224.00 FL	*126.10 FL
17	1		*TAILGATE WIPER	Not Necessary	80.00 FL	*- FL
18	1		*TAILGATE WIPER MOTOR	Jammed	356.00 FL	*356.00 FL
19	1		*REAR BUMPER	Dented	986.00 FL	*915.40 FL
20	2		*REAR BUMPER SIDE RETAINER	Bent	136.00 FL	*136.00 FL
21	2		*REAR BUMPER BRACKET	No such part	96.00 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	385.00 FL	*191.00 FL
23	1		*REAR BUMPER UNDER COVER	Not Necessary	120.00 FL	*- FL
24	2		*REAR BUMPER REFLECTOR	Not Necessary	174.40 FL	*- FL
25	1		*REAR END PANEL	Dented/Bent	580.00 FL	*491.20 FL
26	1		*REAR END PANEL TOP GARNISH	Twisted	249.00 FL	*181.20 FL
27	1		*SPARE TYRE PANEL	Repair	1,088.00 FL	*- FL
28	1		*SPARE TYRE PANEL COVER TRAY	Cracked	427.00 FL	*385.00 FL
29	1		*EXHAUST MUFFLER	Not Necessary	993.00 FL	*- FL
30	4		*EXHAUST MOUNTING	Not Necessary	192.00 FL	*- FL
31	1		*EXHAUST HEAT SHIELD	Not Necessary	171.00 FL	*- FL
32	2		*SIDE BODY PANEL	Not Necessary	2,253.60 FL	*- FL
33	2		*SIDE BODY PANEL INNER TRIM	Not Necessary	1,496.00 FL	*- FL
34	2		*SIDE BODY PANEL INNER SHIELD	Not Necessary	588.00 FL	*- FL
35	2		*SIDE BODY PANEL GLASS MOULDING	Not Necessary	354.40 FL	*- FL
36	1		*ROOF SPOILER	Not Necessary	374.00 FL	*- FL
37	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
38	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
39	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	45.00 FS	*45.00 FS
40	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
41	2		*TAILGATE REFLECTOR LAMP SEAL	Not Necessary	60.00 FS	*- FS
42	2		*SET TAILGATE REFLECTOR LAMP CLIPS	Not Necessary	50.00 FS	*- FS
43	2		*TAILLAMP SEAL	Not Necessary	80.00 FS	*- FS
44	2		*SET TAILLAMP CLIPS	Not Necessary	70.00 FS	*- FS
45	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
46	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

6/7/22, 11:01 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
48	1		*SPARE TYRE PANEL SEALANT	Not Necessary	70.00 FS	*- FS
49	2		*SIDE BODY PANEL SEALANT	Not Necessary	160.00 FS	*- FS
50	2		*SET SIDE BODY PANEL INNER TRIM CLIPS	Not Necessary	110.00 FS	*- FS
51	2		*SET SIDE BODY PANEL INNER SHIELD CLIPS	Not Necessary	64.00 FS	*- FS
52	1		*SET REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS
53	1		*IN CAR CAMERA	Serviceable	350.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					20,900.50	9,270.00
- List Item Discount on L Items 10.00/20.00% (\$\$)					1,915.15	1,777.00
Total Parts (\$\$)					18,985.35	7,493.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING	New	1,800.00	1,000.00
3	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	80.00	50.00
4	REMOVE & REFIT INTERIOR UPHOLSTERY	New	200.00	80.00
5	REMOVE & REFIT TAILGATE COMPONENT	New	100.00	60.00
6	REMOVE & REFIT EXHAUST PIPE	New	180.00	0.00
7	REMOVE & REFIT REVERSE SENSOR AND CHECK	New	100.00	50.00
8	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	60.00
Gross Labour Cost (\$)			4,660.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >