

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22004760/KCY3N2**Date:** 29/06/2022REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21B00023601  
**Claimant Vehicle No :** SMK4593S **Insured Vehicle No :** SJZ5052L  
 Date of Loss: 17/05/2022 Nature of Claim: TP Claim No: DMPC2200206H/02/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4593S**  
 Make & Model: HYUNDAI SANTA FE, 2.4 (A) Engine No: D4HBJU776832  
 Reg. Date: 11/04/2019 (Man. Year: 2018) Chassis No: KMHS381CMKU039202  
 Colour: Metallic Pearl White Odometer: 46561 km  
 Engine Capacity: 2199 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65R17 Rear Tyre Size: 235/65R17  
 Front Left Side: Roadstone 9 mm Rear Left Side: Roadstone 9 mm  
 Front Right Side: Roadstone 9 mm Rear Right Side: Roadstone 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,067.00	4,595.88	4,471.12	49.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,500.00	1,380.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,947.00</b>	<b>6,095.88</b>	<b>5,851.12</b>	<b>48.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	836.29	426.71	409.58	48.98
<b>Nett Amount (S\$)</b>	<b>12,783.29</b>	<b>6,522.59</b>	<b>6,260.70</b>	<b>48.98</b>

INSPECTION

Date of Assignment: 20/05/2022  
 Date Inspected: 23/05/2022 Inspected At: Ah Lim Motor Company (AMK)  
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK  
 Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
<b>Parts:</b>	M1-SUV	HYUNDAI SANTA FE 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK4593S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE W EMBLEM ASSY	Serviceable	879.70 FL	*- FL
2	8		*FRONT GRILLE CLIPS	Not Necessary	16.00 FL	*- FL
3	1		*FRONT BUMPER	Serviceable	586.90 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER LH & RH	Serviceable	30.00 FL	*- FL
5	15		*FRONT BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
6	1		*FRONT BUMPER NO PLATE GARNISH	Cracked	20.60 FL	*20.60 FL
7	1		*FRONT BUMPER LOWER AIR GRILLE	Serviceable	110.10 FL	*- FL
8	1		*FRONT BUMPER LOWER GARNISH	Serviceable	287.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Repair	954.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Serviceable	165.80 FL	*- FL
11	1		*REAR WINDSCREEN MLDG TOP/SIDE/LOWER (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*TAILGATE	Bent	2,326.00 FL	*2,326.00 FL
13	1		*TAILGATE EMBLEM	Necessary	24.60 FL	*24.60 FL
14	1		*TAILGATE SANTAFE LOGO	Necessary	36.80 FL	*36.80 FL
15	1		*TAILGATE 2.2D LOGO	Necessary	21.70 FL	*21.70 FL
16	1		*TAILGATE INNER LOCK	Repair	147.40 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Serviceable	115.40 FL	*- FL
18	1		*REAR BUMPER	Buckled	446.50 FL	*446.50 FL
19	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	50.00 FL	*- FL
20	15		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
21	1		*REAR BUMPER CTR GARNISH	Cracked	509.00 FL	*509.00 FL
22	1		*REAR BUMPER CTR GRILLE	Dented	30.00 FL	*30.00 FL
23	1		*REAR BUMPER LOWER GARNISH	Cracked	185.90 FL	*185.90 FL
24	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	706.80 FL	*- FL
25	2		*REAR BUMPER REFLECTOR MLDG LH & RH	Serviceable	365.20 FL	*- FL
26	2		*REAR BUMPER REVERSE SENSOR INNER LH & RH	Shorted	367.20 FL	*367.20 FL
27	2		*REAR BUMPER REVERSE SENSOR OUTER LH & RH	Serviceable	367.20 FL	*- FL
28	1		*REAR BUMPER REINFORCEMENT	Cracked	270.80 FL	*270.80 FL
29	1		*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 FL	*- FL
30	1		*REAR END PANEL	Repair	739.10 FL	*- FL
31	1		*REAR END PANEL TOP GARNISH	Serviceable	38.30 FL	*- FL
32	1		*REAR EXHAUST PIPE W CHROME	Dented	1,357.00 FL	*1,357.00 FL
33	1		*NUMBER PLATE FRT	Bent	35.00 FS	*35.00 FS
34	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
35	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,310.00</b>	<b>5,721.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,243.00	1,125.22
<b>Total Parts (\$\$)</b>	<b>9,067.00</b>	<b>4,595.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	30.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	90.00	0.00
4	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	80.00	60.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO REALIGN,DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE	New	90.00	60.00
7	TO DISMANTLE ALL DAMAGED PARTS,TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	1,200.00	600.00
8	TO SPRAY FRONT BUMPER,TAILGATE,REAR BUMPER,END PANEL,SPARE TYRE PANEL	New	1,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,880.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >