



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GP 3873K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT O/S DOOR SIDE MIRROR	DAMAGED / CRACKED	1,045.80	1,045.80
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	1,794.40	-
20	FRONT O/S DOOR INNER TRIM BOARD CLIPS @\$5.50	NOT NECESSARY	110.00	-
	LESS 25% DISCOUNT		-737.55	-261.45
			2,212.65	784.35
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT O/S DOOR COMPANY DETAIL STICKER (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<b><u>LABOUR</u></b>			
	TO WIRING CHECK UP FOR AFFECTED DOOR WIRING SYSTEM.		40.00	20.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT O/S DOOR & NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR. }		400.00	220.00
	TO REMOVE & REFIX FRONT O/S DOOR INNER TRIM BOARD & NECESSARY PARTS, TO ENABLE REPAIR NECESSARY PARTS. }		120.00	-
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	500.00	-
	TO RESPRAY TUFF-KOTE FOR AFFECTED ACCIDENT PARTS.	NOT NECESSARY	50.00	-
			1,110.00	240.00
<b>GRAND TOTAL</b>			<b>3,382.65</b>	<b>1,024.35</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,024.35</b>

Report Ref No. CS/FCI22004761/Uty3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.