

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22004762/UEA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_01

Claimant Vehicle No : SLU3952E **Insured Vehicle No :** SHD2658Z

Date of Loss: 20/05/2022 Nature of Claim: TP Claim No: MFL2022D0002707

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU3952E**

Make & Model: BMW 116D, 1.5 D 5DR LED EU6 (A) Engine No: 32415122B37D15A

Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: WBA1V72010V945289

Colour: White Odometer: 68563 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,593.32	4,107.44	6,485.88	61.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	900.00	1,160.00	56.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,653.32	5,007.44	7,645.88	60.43
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	12,653.32	4,000.00	8,653.32	68.39
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,507.45		

INSPECTION

Date of Assignment: 20/05/2022

Date Inspected: 20/05/2022 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
Parts:	144	BMW 116D 1.5 D 5DR LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3952E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,681.32 F	*1,135.20 FL
2	1		*FRONT BUMPER LOGO	Necessary	105.00 F	*105.00 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	198.20 F	*102.30 FL
4	1		*FRONT BUMPER PDC SENSOR O/S	Shorted	186.00 F	*175.00 FL
5	1		*FRONT BUMPER FOG LAMP O/S	Cracked	450.50 F	*322.20 FL
6	1		*FRONT BUMPER FOG LAMP COVER O/S	Twisted	182.30 F	*148.50 FL
7	1		*FRONT BUMPER BEAM	Not Necessary	615.00 F	*- FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
9	1		*HEADLAMP O/S	Cracked	4,954.00 F	*2,285.42 FL
10	1		*FRONT FENDER O/S	Repair	988.00 F	*- FL
11	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	233.00 F	*- FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	50.00 F	*- FL
13	1		*FRONT SPORT RIM O/S	Not Necessary	900.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,593.32	4,323.62
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	216.18
Total Parts (\$\$)	10,593.32	4,107.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	50.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
5	TO DIAGNOSTIC & RESET SYSTEM	New	180.00	80.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	800.00	450.00
Gross Labour Cost (\$\$)			2,060.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >