9/30/22, 2:55 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004766/ANY3Q2

30/09/2022 Date:

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer:

Policy No:

DMCVSNA00122132101

Claimant Vehicle

Pte. Ltd.

Insured Vehicle

GBL1741B

No:

FBF5621U

No:

Date of Loss:

17/05/2022

Nature of Claim: TP Claim No:

SNM22D203479/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBF5621U

Make & Model: Reg. Date:

Engine Capacity:

YAMAHA 135LC, 134cc ES 19/08/2011 (Man. Year: 2011) Engine No: Chassis No: Odometer:

5YP013073 5YP013073

705162 km

Colour:

Red

135 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size:

70/90 R17 Green Devil 6 mm Rear Tyre Size:

90/80 R17

Front Left Side: Front Right Side:

Rear Left Side:

Green Devil 6 mm

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,811.00	1,035.40	775.60	42.83
Miscellaneous Items		0.00	0.00	0.00	
Labour		640.00	390.00	250.00	39.06
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,451.00	1,425.40	1,025.60	41.84
Aj	oproved Total (Overridden) (S\$)		1,100.00		
	Nett Amount (S\$)	2,451.00	1,100.00	1,351.00	55.12

INSPECTION

Date of Assignment:

20/05/2022

Date Inspected:

20/05/2022 Inspected At:

JEC AUTO SERVICE PTE LTD (HQ)

1 KAKI BUKIT AVENUE 6 #02-11 AÚTOBAY

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager:

HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Sep 2022)

Parts: N/A YAMAHA 135LC 134cc ES (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBF5621U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOX	Cut	280.00 FS	*200.00 FS
2	1		*REAR BOX BASE	Damaged	75.00 FS	*75.00 FS
3	1		*REAR BOX BRACKET	Not Necessary	200.00 FS	*- FS
4	1		*REAR EXHAUST PIPE	Repair	350.00 F	*- FL
5	1		*REAR EXHAUST PIPE HEAT SHIELD	Cut	120.00 F	*120.00 FL
6	1		*FOOT REST BRACKET	Bent	75.00 F	*75.00 FL
7	2		*FOOT REST RUBBER	Cut	70.00 F	*70.00 FL
8	1		*SIDE STAND	Cut	68.00 F	*68.00 FL
9	1		*REAR FOOT REST	Cut	38.00 F	*38.00 FL
10	1		*SIDE FAIRING	Cracked	150.00 F	*150.00 FL
11	1		*BALANCER	Cut	30.00 F	*30.00 FL
12	1		*WING MIRROR	Cut	40.00 F	*40.00 FL
13	1		*FRONT WHEEL FENDER	Repair	80.00 F	*- FL
14	1		*ERP UNIT	Cut	170.00 FS	*170.00 FS
15	1		*FOOT LEVER	Bent	65.00 F	*65.00 FL
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,811.00	1,101.00
			- List Item Discoun	0.00	65.60	
				Total Parts (S\$)	1,811.00	1,035.40
			Report was unsubmitted	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR	New	300.00	200.00
2	SPRAY PAINTING	New	300.00	150.00
3	TOWING FEES	New	40.00	40.00
		Gross Labour Cost (S\$)	640.00	390.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >