

TP China.
Hui Rong.

FBF5621U. 2011 August.

Yamaha T135 135cc

SYPO13073

Rear Box	lt	280(SN) 200(SN)
Rear Box Base.	Don't	75(SN) ✓
Rear Box Bracket	new	200(SN) X
Rear Exhaust Pipe.	Rings	350 X
Rear Exhaust Pipe Heat Shield	lt	120. ✓
Foot Rest Bracket	Best	75 ✓
Foot Rest Rubber x02	at	35x2 = 70. ✓
Side Stand.	lt	68 ✓
Rear Foot Rest.	lt	88 ✓
Side Fairing.	Amhd	150 ✓
Balancers	at	30. ✓
Wing Mirror	at	40. ✓
Front wheel Fender	Rings	80 X

FBF5621U.

ERP Unit. Lt 170(SN) ✓

Foot Lever But 65. ✓

656 S/V: 445
590.40

Labour

Spry Painting.

Towing Fees.

~~300~~ 200

~~300~~ 150

40 ✓

390

Total: 1425.40

L/S: 1.1K

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: