LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd. Our File No: CS/CTI22004767/GQY3E2

3 Anson Road, #16-00 Springleaf Tower Date: 07/06/2022 Singapore 079909

REFERENCE

Insured/Claimant: SHEREEN D/O ANWAR BASAH

Policy No: DMPCSNW00176202101

Nature of Claim 22/04/2022 OD SNM22D202787/C01/TANCHC Date of Loss: Claim: No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU936K**

VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI DSG Make & Model:

Engine No: WVWZZZ16ZJM504542 Reg. Date: 28/02/2018 (Man. Year: 2017) Chassis No:

Colour: Black Odometer: 0 km

1197 cc **Engine Capacity:** Market Value/New Car Price: S\$90,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Engine Modification: Handbrake (Serviceable): Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 235/45Z R18 Rear Tyre Size: 235/45Z R18 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,350.00	1,207.80	142.20	10.53
Miscellaneous Items		0.00	0.00	0.00	
Labour		500.00	400.00	100.00	20.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,850.00	1,607.80	242.20	13.09
	Approved Total (Overridden) (S\$)		300.00		
	Nett Amount (S\$)	1,850.00	300.00	1,550.00	83.78

INSPECTION

Date of Assignment: 20/05/2022

KIRALY AUTOMOBILE PRIVATE LIMITED (HQ)

CYV588362

8 KAKI BUKIT AVENUE 4, #06-43, PREMIÈR @ Date Inspected: 20/05/2022 Inspected At:

KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

EXCESS: \$500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Jun 2022)

Parts: N/A VOLKSWAGEN BEETLE CABRIOLET 1.2 TSI DSG (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU936K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Pa	rt No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Broken	980.00 F	*829.00 F
2	1		*FRONT BUMPER GRILLE (WCP)	Cut	160.00 F	*135.00 F
3	1		*FRONT BUMPER HOLDER (WCP)	Broken	50.00 F	*42.00 F
4	1		*FRONT BUMPER BRACKET (WCP)	Broken	40.00 F	*33.00 F
5	1		*FRONT CENTER COVER (WCP)	Broken	70.00 F	*59.00 F
6	1		*FRONT NUMBER PLATE (WCP)	Not Necessary	50.00 F	*-F
F=Fra	anchise part.			Sub Total (S\$)	1,350.00	1,098.00
			+ M	argin on L,N Items 0.00/10.00% (S\$)	0.00	109.80
				Total Parts (S\$)	1,350.00	1,207.80
			Report was uns	submitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount				
<u>Labour Items</u>							
1 SPARK PAIN AND KNOCKING	New	500.00	400.00				
	Gross Labour Cost (S\$)	500.00	400.00				
Report	was unsubmitted during this print-out.						

< END OF ESTIMATES >