



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 1988U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN INNER SEAL	NOT NECESSARY	85.00	-
1	REAR TAILGATE	WARPED / CRACKED	1,450.00	1,399.00
1	REAR TAILGATE LAMP	NOT NECESSARY	325.00	-
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	245.00	-
1	REAR TAILGATE LOGO	NOT NECESSARY	85.00	-
1	REAR TAILGATE RUBBER	NOT NECESSARY	146.00	-
1	REAR TAILGATE "PEUGEOT" EMBLEM	NECESSARY	68.00	68.00
1	REAR TAILGATE "308" EMBLEM	NECESSARY	65.00	65.00
1	REAR TAILGATE "PURE TECH" EMBLEM	NECESSARY	68.00	68.00
1	REAR TAILLAMP-RH	CRACKED	586.00	586.00
1	REAR TAILLAMP LOWER BRACKET	CRACKED	89.00	89.00
1	REAR END PANEL	DENTED / BENT	865.00	865.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	192.00	-
1	REAR BUMPER	DISTORTED	1,065.00	1,065.00
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	485.00	380.00
1	REAR BUMPER REINFORCEMENT	BENT	685.00	685.00
2	REAR BUMPER SIDE RETAINERS	O/S CRACKED	130.00	65.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	28.00	-
1	REAR BUMPER PDC SENSOR	SHORTED	255.00	195.00
1	REAR FENDER-RH	TO REPAIR SEE LABOUR	1,085.00	-
1	REAR FENDER AIR GATE	DISTORTED	68.00	68.00
1	REAR FENDER INNER SHIELD	TORN	182.00	182.00
1	REAR WHEEL RIM-RH	NOT NECESSARY	800.00	-
1	REAR WHEEL HUB WITH BEARING	NOT NECESSARY	325.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	215.00	-
1	REAR KNUCKLE ARM	NOT NECESSARY	286.00	-
	LESS 10% DISCOUNT		-987.80	-578.00
			8,890.20	5,202.00

Report Ref No. CS/AIS22004770/Uvy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR TYRE (SN)	NOT NECESSARY	400.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	50.00
			540.00	90.00
	<u>LABOUR</u>			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.		80.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO APPLY UNDERCOATING.		200.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER-RH.		1,500.00	1,000.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	1,000.00
			3,740.00	2,380.00
GRAND TOTAL			13,170.20	7,672.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. CS/AIS22004770/Uvy3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.