



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

WVWZZ2A4ZJW155925

TP AXA -
Denise.

DATE: 28/05/2022 OUR REF: UAPL1533
REPAIR ESTIMATE YOUR INSURED VOLKSWAGON GOLF NO: SLX4304D

1 FRONT L/H FENDER ASSY	Neu	\$ 774.40	T.
1 FRONT L/H HEADLAMP ASSY	cut	\$ 1,654.20	
1 FRONT BUMPER FACE	Debond	\$ 988.60	
1 FRONT BUMPER L/H INNER HOLDER GARNISH	Neu	\$ 177.30	x.
1 FRONT BUMPER L/H SIDE RETAINER	Neu	\$ 36.40	
10 REAR BUMPER CLIPS	Neu	\$ 55.00	
1 FRONT BUMPER REINFORCEMENT	Perted	\$ 450.00	
1 FRONT BUMPER BLACK SPONGES	includ	\$ 112.30	
1 FRONT BUMPER L/H FOG LAMP COVER	cut	\$ 1,698.80	125.
1 FRONT RADIATOR GRILLE ASSY	Neu	\$ 458.40	x.
1 FRONT WINDSCREEN WASHER TANK	Debond	\$ 245.20	135
1 FRONT SUPPORT PANEL	Neu	\$ 876.50	x.
		\$ 7,527.10	
		\$ 752.71	
		\$ 6,774.39	

LESS 10%.....

LABOUR CHARGES:-

TO DISM/REWIRE REAR DAMAGED PORTION	\$ 100.00	30.
TO PANEL BEAT DAMAGED PORTION	\$ 900.00	300
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 900.00	250.
TO SPRAY UNDERCOATING IN REPAIR	\$ 120.00	x.
TO SEND VEHICLE FOR COMPUTER ALIGNMENT	\$ 120.00	x.
TO DISM/RENEW FRONT AIR CON UNIT AND REFILL GAS	\$ 220.00	x.
	\$ 9,134.39	

total: 3780.85

4/5: 314

03 Days.