

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004780/UPA3Q2**Date:** 09/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800154044
Claimant Vehicle No :	CB6636E	Insured Vehicle No :	SMG6089P
Date of Loss:	19/05/2022	Nature of Claim:	TP
		Claim No:	6342385928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB6636E	Engine No:	1KD2053792
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Chassis No:	JTFST22P300009448
Reg. Date:	24/12/2010 (Man. Year: 2010)	Odometer:	424069 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,930.95	5,778.02	3,152.93	35.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	2,230.00	1,170.00	34.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,330.95	8,008.02	4,322.93	35.06
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	12,330.95	6,400.00	5,930.95	48.10
+ GST 7.00/7.00% (S\$)	863.17	448.00	415.17	48.10
Nett Amount (S\$)	13,194.12	6,848.00	6,346.12	48.10
+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,973.50		

INSPECTION

Date of Assignment:	23/05/2022		
Date Inspected:	23/05/2022	Inspected At:	Think One Autocare Pte Ltd (HQ) No. 60 Jalan Lam Huat #02-32, Carros Centre, 737869 Kranji
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE ASSY	Badly Dented	2,462.00 FL	*2,462.00 FL
2	1		*TAIL GATE TRIM BOARD	Warped / Deformed	428.00 FL	*266.10 FL
3	1		*TAIL GATE LOCK	Dented / Jammed	509.20 FL	*399.50 FL
4	1		*TAIL GATE LOCK CATCH	Not Necessary	45.00 FL	*- FL
5	1		*TAIL GATE OUTER GARNISH	Not Necessary	185.00 FL	*- FL
6	1		*TAIL GATE DAMPER RH	Not Necessary	269.80 FL	*- FL
7	1		*TAIL GATE WEATHERSTRIP	Twisted	245.00 FL	*245.00 FL
8	1		*TAIL GATE (LOGO) EMBLEM	Necessary	165.00 FL	*68.50 FL
9	2		*TAIL GATE STOPPER	Not Necessary	110.00 FL	*- FL
10	1		*REAR END PANEL TOP PLATE	Bent	298.00 FL	*225.10 FL
11	1		*REAR FLOOR PANEL MAT	Not Necessary	422.00 FL	*- FL
12	1		*REAR END PANEL INNER	Badly Dented	936.20 FL	*801.10 FL
13	1		*REAR END PANEL OUTER	Badly Dented	655.00 FL	*655.00 FL
14	2		*TAIL LAMP ASSY R+L	Cracked	1,288.00 FL	*798.20 FL
15	1		*TAIL LAMP LOWER GARNISH RH	Repair	140.30 FL	*- FL
16	1		*REAR BUMPER	Distorted	706.00 FL	*485.10 FL
17	2		*REAR BUMPER SIDE RETAINER R+L	Bent / Cracked	243.00 FL	*243.00 FL
18	1		*EXHAUST TAIL PIPE	Not Necessary	825.00 FL	*- FL
19	1		*TAILLAMP HOUSING PANEL N/S	Dented	466.10 FL	*466.10 FL
20	3		*REAR BUMPER LOWER BRACKETS	Bent	96.00 FL	*96.00 FL
21	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	90.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	62.00 FS	*40.00 FS
23	1		*TOYOTA HIACE STICKER	Not Necessary	45.00 FS	*- FS
24	1		*(70KM/H) STICKER	Necessary	25.00 FS	*10.00 FS
25	8		*TAIL GATE TRIM BOARD CLIP	Necessary	48.00 FS	*30.00 FS
26	1		*REVERSE CAMERA	Not Necessary	420.00 FS	*- FS
27	1		*SET REVERSE SENSOR	Torn	250.00 FS	*200.00 FS
28	1		*JOINT SEAL	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,554.60	7,580.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,623.65	1,802.68
Total Parts (\$\$)	8,930.95	5,778.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REAR DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT -WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ ATTACHMENTS	New	1,200.00	900.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,100.00	900.00
3	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	200.00	80.00
4	TO REMOVE ,REFIT REAR WINDSCREEN GLASS AND WATER TEST	New	250.00	120.00
5	TO REMOVE ,REFIT REAR INTERIOR GARNISHES UPHOLSTERY & SEAT	New	250.00	100.00
6	TO INSTALL REVERSE SENSOR AND TEST FUNCTION	New	100.00	50.00
7	TO APPLY ANTI RUST SOLUTION TO AFFECTED AREAS	New	150.00	80.00
8	TO REMOVE ,REPLACE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$)			3,400.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >