

Not Approved  
 her  
 23/5/22 6 days.  
 2/5 @ 6400

MS140709

**CB6636E TOYOTA HIACE HIGH ROOF**

DATE 20.05.2022

No	Qty	PARTICULAR		DATE	AMOUNT S\$
1	1	TAIL GATE ASSY	body work	2462.00	2,462.00
2	1	TAIL GATE TRIM BOARD	work/pe	266.10	428.00
3	1	TAIL GATE LOCK	work	399.50	509.20
4	1	TAIL GATE LOCK CATCH	11		45.00
5	1	TAIL GATE OUTER GARNISH	11		185.00
6	1	TAIL GATE DAMPER RH	11		269.80
7	1	TAIL GATE WEATHERSTRIP	11		245.00
8	1	TAIL GATE (LOGO) EMBLEM	11		165.00
9	2	TAIL GATE STOPPER	11	55.00	110.00
10	1	REAR END PANEL GARNISH	top plate surf	225.10	298.00
11	1	REAR FLOOR PANEL MAT	11		422.00
12	1	REAR END PANEL INNER	body work	801.10	936.20
13	1	REAR END PANEL OUTER	body work	655.00	755.00
14	2	TAIL LAMP ASSY R+L	one	399.10 x 2 = 798.20	1,288.00
15	1	TAIL LAMP LOWER GARNISH RH	11	644.00	140.30
16	1	REAR BUMPER	11	485.10	706.00
17	2	REAR BUMPER SIDE RETAINER R+L	surf/one	121.50	243.00
18	1	EXHUAUST TAIL PIPE	11		825.00
3pcs tail lamp housing panel r/l 11 \$466.10 ✓					
Rear bumper lower brackets @32 x 3 = 96 surf					
LESS 25%					

No	Qty	PARTICULAR	SPECAIL NETT	AMOUNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT	11	90.00
2	1	REAR WINDSCREEN GLASS INNER SEAL	11	62.00
3	1	TOYOTA HIACE STICKER	11	45.00
4	1	(70 KM/H) STICKER	11	25.00
5	8	TAIL GATE TRIM BOARD CLIP	11	6.00
6	1	REVERSE CAMERA	11	420.00
7	1 set	REVERSE SENSOR	11	250.00
8	1	JOINT SEAL	11	120.00
				\$ 1,060.00

**LABOUR & MISCELLANEOUS:**

AMOUNT S\$

1	To remove rear damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,200.00
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,100.00
3	To transfer tail gate components with all necessary attachments	200.00
4	To remove, refit rear windscreen glass and water test	250.00
5	To remove, refit rear interior garnishes upholstery & Seat	250.00

6	To install reverse sensor and test funtion	100.00	50
7	To apply anti rust solution to affected areas	150.00	80
8	To remove,replace exhuaast pipe	150.00	X
		<u>3,400.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P- 7210.7  
25%  
P- 5408.02  
S.N- 370  
L- 2230  


---

600802  
6406