

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22004786/UPA3Q2**Date:** 14/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SDN6895Z **Insured Vehicle No :** GBJ436A

Date of Loss: 20/05/2022 Nature of Claim: TP Claim No: MFL2022D0002696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN6895Z**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU204478

Reg. Date: 19/06/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU702762

Colour: White Odometer: 85084 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: LAUFENN 6 mm Rear Left Side: LAUFENN 6 mm

Front Right Side: LAUFENN 6 mm Rear Right Side: LAUFENN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,779.50	4,363.92	7,415.58	62.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	1,670.00	2,560.00	60.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,009.50	6,033.92	9,975.58	62.31
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	16,009.50	4,800.00	11,209.50	70.02
+ Car Rental (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,307.45		

INSPECTION

Date of Assignment: 21/05/2022

Date Inspected: 21/05/2022 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDN6895Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,266.20 F	*1,782.00 FL
2	2		*BOOTLID REFLECTORS	Not Necessary	900.00 F	*- FL
3	1		*BOOTLID INNER LOCK	Bent	188.90 F	*145.00 FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	299.20 F	*166.00 FL
5	1		*REAR BUMPER	Deformed / Dented	845.20 F	*498.00 FL
6	2		*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
7	1		*REAR BUMPER BEAM	Bent	516.80 F	*341.00 FL
8	1		*REAR BUMPER LOWER GARNISH	Deformed	699.00 F	*450.00 FL
9	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 F	*130.00 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
11	1		*TAILLAMPS	N/S Cracked	1,370.00 F	*580.50 FL
12	1		*REAR END PANEL	Dented	785.20 F	*585.90 FL
13	1		*REAR END PANEL BUZZLE SENSOR	Cracked	250.00 F	*220.00 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	199.00 F	*199.00 FL
15	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
16	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	615.00 F	*- FL
17	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
19	1		*BOOTLID TOP SPOILER	Repair	800.00 FS	*- FS
20	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,779.50	5,392.40
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,028.48
Total Parts (\$)	11,779.50	4,363.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	TO RESET & REPROGRAMMING SYSTEM	New	180.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,800.00	800.00
Gross Labour Cost (\$)			4,230.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >