

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004791/APA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900236568
Claimant Vehicle No :	SLM9779S	Insured Vehicle No :	SMQ2697H
Date of Loss:	14/05/2022	Nature of Claim:	TP
		Claim No:	4154014220SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9779S	Engine No:	R16B21601157
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT000878
Reg. Date:	24/01/2017 (Man. Year: 2016)	Odometer:	81228 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,544.10	2,140.80	5,403.30	71.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,260.00	930.00	42.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,734.10	3,400.80	6,333.30	65.06
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	9,734.10	2,700.00	7,034.10	72.26
+ GST 7.00/7.00% (S\$)	681.39	189.00	492.39	72.26
Nett Amount (S\$)	10,415.49	2,889.00	7,526.49	72.26
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,189.00		

INSPECTION

Date of Assignment:	18/05/2022	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	18/05/2022 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,120.00 F	*687.00 FL
2	1		*REAR BOOT LID EMBLEM LOGO	Necessary	75.00 F	*45.00 FL
3	1		*REAR BOOT LID EMBLEM LOGO CLIPS (3 PCS)	Necessary	19.50 F	*10.00 FL
4	1		*REAR BOOT LID CIVIC LOGO	Necessary	45.00 F	*45.00 FL
5	1		*REAR BOOT LID VTEC LOGO	Necessary	40.00 F	*40.00 FL
6	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	624.00 F	*- FL
7	1		*REAR BOOT LID INNER RUBBER	Cut	255.00 F	*119.00 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	485.00 F	*- FL
10	2		*REAR TAIL LAMP	Not Necessary	830.00 F	*- FL
11	1		*REAR END PANEL	Repair	455.00 F	*- FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	214.00 F	*214.00 FL
13	2		*REAR BUMPER INNER RETAINER	Not Necessary	264.00 F	*- FL
14	1		*REAR BUMPER	Deformed	862.40 F	*630.00 FL
15	2		*REAR BUMPER SIDE BRACKET	Necessary	230.40 F	*90.00 FL
16	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 F	*240.00 FL
17	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
18	1		*REAR BUMPER CENTER LOWER COVER	Deformed	385.00 F	*280.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	448.00 F	*246.00 FL
20	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	196.40 F	*- FL
21	2		*REAR BUMPER SIDE REFLECTOR CHROME	Not Necessary	210.40 F	*- FL
22	2		*REAR EXHAUST CHROME PIPE	Not Necessary	320.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,544.10	2,676.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	535.20
Total Parts (\$\$)	7,544.10	2,140.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	40.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
4	GUM	New	50.00	0.00
5	TUFF KOTE	New	120.00	40.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	PANEL BEATING	New	800.00	500.00
8	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$\$)			2,190.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >