

TP AIG.
Asher.

SJR8790L 2009 July.
Subaru Impreza 1498cc
JF1GH3KW49G03146Y

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Reer Bumper

Distorted

654.10 ✓

30(SN) ✓

Reer Bumper Clips.

new

Reer Bumper Side Holder x02

new

32 x 2 = 64 ✓

Reer Bumper Reinforcement

distorted

232.50 ✓

Reer Bumper Lower Spoiler

Deformed

~~1000(SN)~~ 200(SN)

29.10

Reer Bumper Reflector x02

LH crushed

29.1 x 2 = 58.20

~~280(SN)~~ 200(SN)

Reverse Sensor

Damaged

481.60 +

Reer End Panel

XH new

60(SN) X

1029.70

Reer End Panel Sealant

XH new

823.76

Taillamp LH.

XH new

366.30 X SN 900

Panel Beating.

Spray Painting.

Wiring.

To spray tuff coat

To remove reverse sensor

~~600~~ 300

~~800~~ 400

780

~~50~~ 30

150 X

~~100~~ 50

total: 2503.76

L/S: 2K.

030hrs.

2K
3 days