

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004793/AEA3Q2**Date:** 21/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000059
Claimant Vehicle No :	SJJ3410J	Insured Vehicle No :	GBK8229Z
Date of Loss:	16/05/2022	Nature of Claim:	TP
		Claim No:	5160213663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ3410J	Engine No:	2122675
Make & Model:	DAIHATSU MATERIA, 1.5 (A)	Chassis No:	JDAM402S001012801
Reg. Date:	09/09/2008 (Man. Year: 2008)	Odometer:	176542 km
Colour:	Maroon		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,840.27	5,494.95	3,345.32	37.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,780.00	2,400.00	57.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,020.27	7,274.95	5,745.32	44.13
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	13,020.27	5,800.00	7,220.27	55.45
+ GST 7.00/7.00% (S\$)	911.42	406.00	505.42	55.45
Nett Amount (S\$)	13,931.69	6,206.00	7,725.69	55.45
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,633.45		

INSPECTION

Date of Assignment:	18/05/2022	
Date Inspected:	18/05/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Distorted	1,259.00 FL	*895.00 FL
2	1		*RH FRONT DOOR HINGE	Bent	178.00 FL	*178.00 FL
3	1		*RH FRONT DOOR CHECKER	Not Necessary	65.00 FL	*- FL
4	1		*RH FRONT DOOR WEATHERSTRIPE	Cut	289.00 FL	*289.00 FL
5	1		*RH FRONT DOOR GLASS	Shattered	452.00 FL	*452.00 FL
6	1		*RH FRONT DOOR GLASS OUTER MOULDING	Deformed	127.00 FL	*127.00 FL
7	1		*RH FRONT DOOR GLASS INNER RUBBER	Not Necessary	145.00 FL	*- FL
8	1		*RH FRONT DOOR GLASS OUTER GARNISH	Not Necessary	65.00 FL	*- FL
9	1		*RH FRONT DOOR OUTER HANDLER	Not Necessary	112.00 FL	*- FL
10	1		*RH FRONT DOOR LOCK	Damaged	108.00 FL	*108.00 FL
11	1		*RH FRONT DOOR INNER TRIM BOARD	Cracked	548.00 FL	*395.00 FL
12	1		*RH FRONT DOOR POWER WINDOW MOTOR	Not Necessary	658.00 FL	*- FL
13	1		*RH FRONT DOOR POWER WINDOW MOTOR GEAR	Damaged	445.00 FL	*445.00 FL
14	1		*RH FRONT DOOR BLACK STICKER	Necessary	78.00 FL	*78.00 FL
15	1		*RH FRONT DOOR WIRE HARNESS	Not Necessary	848.00 FL	*- FL
16	1		*RH FRONT DOOR POWER WINDOW SWITCH WITH HOLDER	Cracked	287.00 FL	*287.00 FL
17	1		*RH FRONT DOOR ARM REST CUSHION	Not Necessary	69.00 FL	*- FL
18	1		*RH FRONT DOOR MIRROR	Cracked	658.00 FL	*658.00 FL
19	1		*RH FRONT DOOR MIRROR COVER	Not Necessary	98.00 FL	*- FL
20	1		*RH FRONT DOOR MIRROR INNER GARNISH COVER	Cracked	23.00 FL	*23.00 FL
21	1		*RH FRONT DOOR PILLAR PANEL (OUTER)	Repair	783.00 FL	*- FL
22	1		*RH FRONT DOOR CENTER PILLAR (OUTER)	Dented	882.00 FL	*882.00 FL
23	1		*RH FRONT DOOR CENTER PILLAR INNER GARNISH	Not Necessary	116.20 FL	*- FL
24	1		*RH FRONT DOOR PILLAR LOWER GARNISH	Deformed	98.00 FL	*98.00 FL
25	1		*RH FRONT DASHBOARD AIR VENT	Not Necessary	83.00 FL	*- FL
26	1		*RH FRONT STEP PANEL GARNISH	Deformed	78.00 FL	*78.00 FL
27	1		*RH ROCKER PANEL (OUTER)	Dented	554.00 FL	*554.00 FL
28	1		*RH FRONT DOOR INNER SPEAKER	Cracked	350.00 FS	*120.00 FS
29	1		*RH FRONT DOOR GLASS SOLAR FILM	Necessary	180.00 FS	*150.00 FS
30	1		*RH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
31	1		*RH ROCKER PANEL GARNISH	Deformed	450.00 FS	*450.00 FS
32	1		*RH ROCKER PANEL GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,206.20	6,327.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,365.93	832.05
Total Parts (\$\$)	8,840.27	5,494.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	700.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	750.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	New	200.00	60.00
5	LABOUR FOR REMOVE & REFIX RH FRONT INNER GARNISH /CARPET /UPHOLSTERY /ROOF LINING	New	300.00	80.00
6	LABOUR FOR REMOVE & TRANSFER ALL REAR DOOR FITTING	New	300.00	80.00
7	LABOUR FOR CLEAN & VACUUM SHATTERED GLASS INCLUDE REMOVE & REFIX FRONT DASHBOARD /RH AIR CON AIR VENT	New	300.00	80.00
Gross Labour Cost (S\$)			4,180.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >