

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004794/RPA3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800076655
Claimant Vehicle No :	SHB5798T	Insured Vehicle No :	SMC4990X
Date of Loss:	13/05/2022	Nature of Claim:	TP
		Claim No:	9509570191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5798T		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR8284578
Reg. Date:	19/12/2017 (Man. Year: 2017)	Chassis No:	JTDMKB3FU603579346
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,678.34	932.93	14,745.41	94.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,986.00	1,450.00	2,536.00	63.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,664.34	2,382.93	17,281.41	87.88
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	19,664.34	2,200.00	17,464.34	88.81
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (7.5 x S\$70.00/day) (S\$)		525.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,982.00		
Global Sum Settlement (S\$)		2,950.00		

INSPECTION

Date of Assignment:	17/05/2022	
Date Inspected:	17/05/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,REAR DOOR LH (DISC 25%)	Bent	1,243.90 F	*932.93 F
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
3	2		*PAD ,RR BUMPER RH & LH ,1	Not Necessary	3.80 F	*- F
4	2		*PAD ,RR BUMPER RH & LH ,2	Not Necessary	3.80 F	*- F
5	2		*PAD ,RR BUMPER RH & LH ,3	Not Necessary	3.80 F	*- F
6	1		*PAD ,RR BUMPER CTR	Not Necessary	2.20 F	*- F
7	2		*SEAL ,RR BUMPER ARM ,RH & LH	Not Necessary	11.00 F	*- F
8	2		*STOPPER ,RR BUMPER ,RH & LH	Not Necessary	4.30 F	*- F
9	1		*RETAINER ,RR BUMPER ,RH	Not Necessary	112.70 F	*- F
10	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	111.50 F	*- F
11	1		*SEAL ,RR BUMPER ,LH	Not Necessary	85.20 F	*- F
12	1		*CLIPS PIECE ,FRT & RR BUMPER	Not Necessary	1.50 F	*- F
13	1		*GUARD ,RR BUMPER LOWER	Not Necessary	558.30 F	*- F
14	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
15	1		*ANTENNA ,ELECTRICAL KEY	Not Necessary	60.30 F	*- F
16	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
17	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Not Necessary	438.10 F	*- F
18	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Not Necessary	438.10 F	*- F
19	1		*LENS & BODY ASSY ,RR BUMPER ,RH	Not Necessary	486.80 F	*- F
20	1		*LENS & BODY ASSY ,RR BUMPER ,LH	Not Necessary	486.80 F	*- F
21	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	234.30 F	*- F
22	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
23	1		*PANEL SUB ASSY ,FRONT DOOR LH	Not Necessary	1,249.60 F	*- F
24	1		*STICKER STRIDES TAXI (DOOR)	Not Necessary	60.00 F	*- F
25	1		*PILLAR ,CENTER BODY ,OUTER LH	Not Necessary	313.40 F	*- F
26	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Not Necessary	83.30 F	*- F
27	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Not Necessary	73.30 F	*- F
28	1		*DOOR REAR MOTOR ASSY ,POWER WINDOW	Not Necessary	768.60 F	*- F
29	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY ,LH	Not Necessary	200.70 F	*- F
30	1		*MEMBER SUB-ASSY ,RAIL ROOT SIDE REAR LH	Not Necessary	279.20 F	*- F
31	1		*CHECK ASSY ,REAR DOOR	Not Necessary	153.50 F	*- F
32	1		*WEATHERSTRIP ,REAR DOOR LH	Not Necessary	174.40 F	*- F
33	1		*DOOR LOCK REAR ,LH	Not Necessary	544.70 F	*- F
34	1		*DOOR REAR LOCK COVER	Not Necessary	8.90 F	*- F
35	1		*MOULDING ASSY ,REAR DOOR BELT LH	Not Necessary	109.80 F	*- F
36	1		*WIRE ,REAR DOOR ,LH	Not Necessary	206.70 F	*- F
37	2		*REAR DOOR SPEAKER ASSY ,RADIO RH & LH	Not Necessary	985.70 F	*- F
38	2		*PATCH ,SIDE PANEL REAR END ,RH & LH	Not Necessary	33.70 F	*- F
39	1		*LINER ,REAR FENDER ,LH	Not Necessary	135.80 F	*- F
40	2		*HUB & BEARING ASSY ,RH & LH	Not Necessary	554.20 F	*- F
41	1		*TYRE	Not Necessary	126.74 F	*- F
42	1		*HUB & BEARING ASSY WITH SPEED SENSOR REAR	Not Necessary	610.20 F	*- F
43	1		*LID ASSY ,FUEL FILLER OPENING	Not Necessary	164.10 F	*- F
44	1		*STICKER PETROL ONLY	Not Necessary	7.80 F	*- F
45	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Repair	576.00 F	*- F
46	1		*COVER ,RR BUMPER ASSY	Repair	423.90 F	*- F
47	1		*FILLER ,RR BUMPER LH	Repair	119.90 F	*- F
48	1		*PANEL SUB-ASSY ,FENDER REAR LH	Repair	824.80 F	*- F
49	1		*WHEEL DISC	Repair	1,879.40 F	*- F

F=Franchise part.

Total Parts (\$) **15,678.34** **932.93**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	2,232.00	750.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	40.00
5	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	100.00	40.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
7	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			3,986.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >