

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004796/BQY3Q2  
**Date:** 16/05/2023**REFERENCE**

|                              |   |                             |                    |           |                         |
|------------------------------|---|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSNW00078612200 |           |                         |
| <b>Claimant Vehicle No :</b> | SGV3737P                                      | <b>Insured Vehicle No :</b> | SNE4743X           |           |                         |
| Date of Loss:                | 19/05/2022                                    | Nature of Claim:            | TP                 | Claim No: | SNM22D203487/C02/TANCHC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |   |             |                   |  |  |
|-----------------------------|---|-------------|-------------------|--|--|
| Reg No:                     | <b>SGV3737P</b>                         |             |                   |  |  |
| Make & Model:               | VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A) | Engine No:  | CAXF83852         |  |  |
| Reg. Date:                  | 30/11/2016 (Man. Year: 2015)            | Chassis No: | WVWZZZ16ZGM014654 |  |  |
| Colour:                     | White                                   | Odometer:   | 85271 km          |  |  |
| Engine Capacity:            | 1390 cc                                 |             |                   |  |  |
| Market Value/New Car Price: | N/A                                     |             |                   |  |  |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>       |             |                   |  |  |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/40 R18    | Rear Tyre Size:  | 225/40 R18    |
| Front Left Side:  | Goodyear 6 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b>             | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b>    |              |
|--|-------------------------------|-------------------|-------------------|------------------|--------------|
| Parts                                    | 14,641.73                     | 6,487.37          | 8,154.36          | 55.69            |              |
| Miscellaneous Items                      | 0.00                          | 0.00              | 0.00              |                  |              |
| Labour                                   | 4,800.00                      | 1,940.00          | 2,860.00          | 59.58            |              |
| Paintwork Labour                         | 0.00                          | 0.00              | 0.00              |                  |              |
| Towing                                   | 0.00                          | 0.00              | 0.00              |                  |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>19,441.73</b>              | <b>8,427.37</b>   | <b>11,014.36</b>  | <b>56.65</b>     |              |
| <b>Approved Total (Overridden) (S\$)</b> |                               | <b>6,750.00</b>   |                   |                  |              |
|  | <b>(S\$)</b>                  | 19,441.73         | 6,750.00          | 12,691.73        | 65.28        |
|  | <b>+ GST 8.00/8.00% (S\$)</b> | 1,555.34          | 540.00            | 1,015.34         | 65.28        |
|  | <b>Nett Amount (S\$)</b>      | <b>20,997.07</b>  | <b>7,290.00</b>   | <b>13,707.07</b> | <b>65.28</b> |

**INSPECTION**

|                             |            |   |
|-----------------------------|------------|---|
| Date of Assignment:         | 27/05/2022 |   |
| Date Inspected:             | 23/05/2022 | Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)<br>8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 9.0 days   |   |

**Adjuster:** Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 16 May 2023)  |
| <b>Parts:</b> 143  | VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SGV3737P) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOTLID                         | Bent          | 2,080.80 FL | *1,875.00 FL |
| 2   | 1   |          | *REAR BOOTLID EMBLEM                  | Necessary     | 133.83 FL   | *92.00 FL    |
| 3   | 1   |          | *REAR BOOTLID HINGE RH                | Not Damaged   | 188.78 FL   | *- FL        |
| 4   | 1   |          | *REAR BOOTLID HINGE LH                | Not Damaged   | 188.78 FL   | *- FL        |
| 5   | 1   |          | *REAR BOOTLID REFLECTOR LAMP RH       | Not Damaged   | 320.99 FL   | *- FL        |
| 6   | 1   |          | *REAR BOOTLID REFLECTOR LAMP LH       | Not Damaged   | 320.99 FL   | *- FL        |
| 7   | 1   |          | *REAR BOOTLID LOCK                    | Not Damaged   | 233.89 FL   | *- FL        |
| 8   | 1   |          | *REAR BOOTLID WEATHERSTRIP            | Not Damaged   | 269.89 FL   | *- FL        |
| 9   | 1   |          | *REAR TAILLAMP ASSEMBLY RH            | Not Damaged   | 420.83 FL   | *- FL        |
| 10  | 1   |          | *REAR TAILLAMP ASSEMBLY LH            | Broken        | 420.83 FL   | *382.00 FL   |
| 11  | 1   |          | *REAR TAILLAMP LOWER BRACKET RH       | Not Damaged   | 83.43 FL    | *- FL        |
| 12  | 1   |          | *REAR TAILLAMP LOWER BRACKET LH       | Broken        | 83.43 FL    | *83.43 FL    |
| 13  | 1   |          | *REAR TAILLAMP PANEL RH               | Not Damaged   | 485.80 FL   | *- FL        |
| 14  | 1   |          | *REAR TAILLAMP PANEL LH               | Not Damaged   | 485.80 FL   | *- FL        |
| 15  | 1   |          | *REAR BUMPER                          | Broken        | 1,355.34 FL | *1,355.34 FL |
| 16  | 1   |          | *REAR BUMPER SPONGE                   | No such part  | 143.61 FL   | *- FL        |
| 17  | 1   |          | *REAR BUMPER REINFORCEMENT            | Not Damaged   | 650.77 FL   | *- FL        |
| 18  | 1   |          | *REAR BUMPER BRACKET RH               | Not Damaged   | 91.28 FL    | *- FL        |
| 19  | 1   |          | *REAR BUMPER BRACKET LH               | Broken        | 91.28 FL    | *91.28 FL    |
| 20  | 1   |          | *REAR BUMPER GUIDE RH                 | Not Damaged   | 91.28 FL    | *- FL        |
| 21  | 1   |          | *REAR BUMPER GUIDE LH                 | Not Damaged   | 91.28 FL    | *- FL        |
| 22  | 1   |          | *REAR BUMPER ATTACHMENT STRIP         | Not Damaged   | 84.92 FL    | *- FL        |
| 23  | 1   |          | *REAR BUMPER LOWER SPOILER            | Not Damaged   | 502.15 FL   | *- FL        |
| 24  | 1   |          | *REAR BUMPER REFLECTOR RH             | Not Damaged   | 87.43 FL    | *- FL        |
| 25  | 1   |          | *REAR BUMPER REFLECTOR LH             | Broken        | 87.43 FL    | *87.43 FL    |
| 26  | 1   |          | *REAR END PANEL                       | Dented        | 1,206.00 FL | *1,206.00 FL |
| 27  | 1   |          | *REAR END PANEL TOP GARNISH           | Not Damaged   | 145.75 FL   | *- FL        |
| 28  | 1   |          | *REAR FENDER LH                       | Dented        | 1,858.05 FL | *1,615.00 FL |
| 29  | 1   |          | *REAR FENDER AIR VENT LH              | Broken        | 65.15 FL    | *65.15 FL    |
| 30  | 1   |          | *REAR FENDER INNER TRIM LH            | Not Damaged   | 396.65 FL   | *- FL        |
| 31  | 1   |          | *REAR FENDER INNER SHIELD LH          | Not Damaged   | 302.15 FL   | *- FL        |
| 32  | 1   |          | *REAR NUMBER PLATE                    | Not Necessary | 50.00 FS    | *- FS        |
| 33  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 50.00 FS    | *30.00 FS    |
| 34  | 1   |          | *SET REAR TAILLAMP CLIPS              | No such part  | 50.00 FS    | *- FS        |
| 35  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 36  | 1   |          | *SET REAR FENDER INNER SHIELD CLIPS   | Not Necessary | 40.00 FS    | *- FS        |
| 37  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS     | Not Necessary | 80.00 FS    | *- FS        |
| 38  | 1   |          | *SET REAR BOOTLID INNER TRIM CLIPS    | Not Necessary | 50.00 FS    | *- FS        |
| 39  | 1   |          | *REAR WINDSCREEN GLASS SEALANT        | Not Necessary | 150.00 FS   | *- FS        |
| 40  | 1   |          | *REAR BOOTLID SEALANT                 | Necessary     | 150.00 FS   | *30.00 FS    |
| 41  | 1   |          | *REAR END PANEL SEALANT               | Necessary     | 150.00 FS   | *30.00 FS    |
| 42  | 1   |          | *REAR FENDER LH SEALANT               | Necessary     | 150.00 FS   | *30.00 FS    |
| 43  | 1   |          | *REAR BOOTLID TOP SPOILER             | No such part  | 800.00 FS   | *- FS        |
| 44  | 1   |          | *SET REAR BUMPER REVERSE SENSOR       | Scratched     | 450.00 FS   | *200.00 FS   |
| 45  | 1   |          | *REAR BOOTLID REVERSE CAMERA          | Not Damaged   | 750.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars   | Lab.Type | Repairer's                     | Amount          |
|---------------------|---|----------|--------------------------------|-----------------|
| <b>Labour Items</b> |   |          |                                |                 |
| 1                   | TO PANEL BEAT ,REMOVE & REFIX PARTS                                     | New      | 1,600.00                       | 1,000.00        |
| 2                   | TO SPRAY PAINT AFFECTED AREAS   | New      | 1,400.00                       | 800.00          |
| 3                   | WIRING & BULB CHECK   | New      | 100.00                         | 0.00            |
| 4                   | TO REMOVE & REFIX REAR WINDSCREEN GLASS                                 | New      | 150.00                         | 0.00            |
| 5                   | TO TRANSFER REAR BOOTLID MECHANISM                                      | New      | 150.00                         | 80.00           |
| 6                   | TO REMOVE & REFIX REAR REVERSE CAMERA                                   | New      | 150.00                         | 0.00            |
| 7                   | TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR                            | New      | 120.00                         | 60.00           |
| 8                   | TO REMOVE & REFIX REAR EXHAUST PIPE                                     | New      | 150.00                         | 0.00            |
| 9                   | TO APPLY ANTI RUST ON AFFECTED PARTS                                    | New      | 150.00                         | 0.00            |
| 10                  | TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS             | New      | 150.00                         | 0.00            |
| 11                  | TO CONDUCT WATER LEAK TEST  | New      | 100.00                         | 0.00            |
| 12                  | TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT PROGRAMMING & CALIBRATION | New      | 580.00                         | 0.00            |
|                     |   |          | <b>Gross Labour Cost (S\$)</b> | <b>4,800.00</b> |
|                     |   |          |                                | <b>1,940.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >