

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004798/AQY3M4**Date:** 27/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00069252101

**Claimant Vehicle No :** GBL925U **Insured Vehicle No :** GBK1182U

Date of Loss: 19/05/2022 Nature of Claim: TP Claim No: SNM22D203481/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBL925U**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M) Engine No: 1KDB069488

Reg. Date: 11/03/2021 (Man. Year: 2020) Chassis No: JTFHT02P200251386

Colour: Silver Odometer: 24401 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,268.90	3,192.37	3,076.53	49.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	910.00	1,270.00	58.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,448.90</b>	<b>4,102.37</b>	<b>4,346.53</b>	<b>51.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,448.90</b>	<b>3,250.00</b>	<b>5,198.90</b>	<b>61.53</b>

**INSPECTION**

Date of Assignment: 27/05/2022

Date Inspected: 24/05/2022 Inspected At: CHENG MOTOR WORK CO. (HQ)  
1 KAKI BUKIT AVE 6 #01-83  
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL925U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	580.10 F	*580.10 FL
2	1		*FRONT BUMPER SIDE RETAINER R/H	Cracked	151.20 F	*151.20 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	470.10 F	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER R/H	Missing	121.30 F	*121.30 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	268.10 F	*- FL
6	1		*FRONT DOOR ASSY R/H	Dented	1,999.70 F	*1,438.00 FL
7	1		*FRONT DOOR HINGE TOP	Not Necessary	90.10 F	*- FL
8	1		*FRONT DOOR HINGE LOWER	Not Necessary	190.10 F	*- FL
9	1		*FRONT DOOR SIDE MIRROR ASSY R/H	Cracked	1,272.70 F	*1,050.00 FL
10	1		*FRONT HEAD LAMP R/H	Cut	953.60 F	*744.00 FL
11	1		*FRONT STEP GARNISH L/H	Cut	171.90 F	*171.90 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					6,268.90	4,256.50
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	1,064.13
Total Parts (\$\$)					6,268.90	3,192.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR KNOCKING FLOOR PANEL, WELDING, CUTTING, REPAIRING AND REPLACEMENT OF PARTS.	New	800.00	400.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	1,000.00	400.00
3	TO DISMANTLE AND TRANSFER DOOR MECHANICAL	New	150.00	80.00
4	TO CHECK WIRING	New	80.00	30.00
5	TO APPLY RUST- PROOFING	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,180.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >