

# CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185/6 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

JTFHT02P200251386

23/5/2022

China Taiping Insurance (S) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower.

Singapore 079909

Attn: motor claims Dept

Xiao Chen.

Estimate cost of repair vehicle no: GBL925U

Front bumper *replaced*  
Front bumper side retainer R/h *could*  
Front bumper reinforcement *new*  
Front bumper fog lamp cover R/h *missing*  
Front bumper lower grille *new*  
Front door assy R/h *replaced*  
Front door hinge top *green*  
Front door hinge lower  
Front door side mirror assy R/h *could*  
Front Head lamp R/h *cut*  
Front Step garnish L/h *cut*

580.10 ✓  
151.20 ✓  
470.10 +  
121.30 ✓  
268.10 +  
~~1999.70~~ 1438  
90.10 +  
190.10 +  
~~1272.70~~ 1050  
~~953.60~~ 744  
171.90 ✓

4256.5  
3192.37

Labour for knocking floor Panel, welding, cutting, repairing

And replacement of parts.

To spray paint on the damage parts.

To dismantle and transfer door mechanical

To check wiring

To apply rust- proofing

800.00 400  
1000.00 400  
150.00 80  
80.00 30  
150.00 +  
910

Adnan Li

L/S 24/05/22.

04 pages

Total 4102.37 2

L/S: 3250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: