



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 3894K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP RH	CRACKED	324.70	324.70
1	TAIL LAMP LOWER GARNISH	SCRATCHED	99.80	99.80
1	REAR BUMPER	SCRATCHED	481.80	481.80
	LESS 25% DISCOUNT		-226.58	-226.58
			679.72	679.72
	<u>LABOUR</u>			
	TO DISMANTLE AND REPLACE OF THE ACCIDENT DAMAGED PARTS; TO HEAT/WELD, CUT-OFF THE REAR FENDER LOWERED LH, TAIL LAMP LOWERED GARNISH LH, REAR BUMPER INCLUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME.		600.00	300.00
	TO PUTTY AND SPRAY PAINTING ON REAR FENDER LOWERED LH, TAIL LAMP LOWERED GARNISH LH, REAR BUMPER INCLUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME.		600.00	500.00
	TO APPLY RUSTPROOFING.		60.00	30.00
			1,260.00	830.00
	GRAND TOTAL		1,939.72	1,509.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI22004801/Vny3m4

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.