

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22004803/VQCE2

Date: 26/08/2022

REFERENCE

Insured/Claimant: ONG SHENG YONG, JOEL Policy No: DMPCSNA00037412201

Date of Loss: 08/05/2022

Nature of Claim: OD

Claim No: SNM22D203195/C01/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG1195Z**

Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE (A)

Engine No: 28291480069123

Reg. Date: 21/02/2020 (Man. Year: 2018)

Chassis No: WDD1770872V015553

Colour: White

Odometer: 0 km

Engine Capacity: 1332 cc

Market Value/New Car Price: S\$148,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,609.00	9,421.00	7,188.00	43.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	2,320.00	930.00	28.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,859.00	11,741.00	8,118.00	40.88
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	19,359.00	11,241.00	8,118.00	41.93
+ GST 7.00/7.00% (S\$)	1,355.13	786.87	568.26	41.93
Nett Amount (S\$)	20,714.13	12,027.87	8,686.26	41.93

INSPECTION

Date of Assignment: 20/05/2022

Date Inspected: 24/05/2022 Inspected At:

Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Aug 2022)

Parts: 144 MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG1195Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Dented	1,100.00 F	*1,100.00 F
2	1		*REAR BUMPER RETAINER LH (WCP)	Not Necessary	75.00 F	*- F
3	1		*REAR BUMPER PDC SENSOR (WCP)	Serviceable	110.00 F	*- F
4	1		*REAR FENDER LH (WCP)	Dented	2,000.00 F	*2,000.00 F
5	1		*REAR FENDER INNER SHIELD LH (WCP)	Cut	90.00 F	*90.00 F
6	1		*FUEL TANK CAP (WCP)	Repair	35.00 F	*- F
7	1		*REAR DOOR PANEL LH (WCP)	Dented	1,200.00 F	*1,200.00 F
8	1		*REAR DOOR HANDLE LH (WCP)	Bent	330.00 F	*330.00 F
9	1		*REAR DOOR INNER TRIM BOARD LH (WCP)	Serviceable	400.00 F	*- F
10	1		*REAR DOOR REGULATOR LH (WCP)	Serviceable	480.00 F	*- F
11	1		*REAR DOOR REGULATOR MOTOR LH (WCP)	Serviceable	300.00 F	*- F
12	1		*REAR DOOR LOCK LH (WCP)	Jammed	380.00 F	*380.00 F
13	1		*REAR DOOR CHECKER LH (WCP)	Serviceable	70.00 F	*- F
14	1		*REAR DOOR WEATHERSTRIP LH (WCP)	Cut	200.00 F	*200.00 F
15	1		*PILLAR C (WCP)	Serviceable	780.00 F	*- F
16	1		*REAR RIM LH (WCP)	Scratched	1,450.00 F	*1,000.00 F
17	1		*REAR KNUCKLE ARM LH (WCP)	Serviceable	900.00 F	*- F
18	1		*REAR KNUCKLE ARM BEARING LH (WCP)	Bent	350.00 F	*350.00 F
19	1		*REAR UPPER ARM LH (WCP)	Bent	1,100.00 F	*220.00 F
20	1		*REAR LOWER ARM LH (WCP)	Bent	200.00 F	*200.00 F
21	1		*REAR SHOCK ABSORBER LH (WCP)	Bent	210.00 F	*210.00 F
22	1		*REAR CONTROL ARM LH (WCP)	Serviceable	110.00 F	*- F
23	1		*BRAKE SENSOR (WCP)	Serviceable	10.00 F	*- F
24	1		*CROSSMEMBER (WCP)	Serviceable	1,400.00 F	*- F
25	1		*CROSSMEMBER LOWER COVER (WCP)	Serviceable	80.00 F	*- F
26	1		*ABS SENSOR (WCP)	Bent	50.00 F	*50.00 F
27	1		*SIDE SKIRT LH (WCP)	Cut	720.00 F	*720.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR TRAILNG ARM LH (WCP)	Bent	160.00 F	*160.00 F
29	1		*REAR TYRE	Cut	800.00 FS	*300.00 FS
30	1		*REAR QUARTER GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR DOOR INNER TRIM BOARD	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	15,180.00	8,600.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,429.00	821.00
Total Parts (S\$)	16,609.00	9,421.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING & LIGHTING SYSTEM	New	100.00	30.00
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	New	200.00	60.00
3	REMOVE AND REFIT REAR DOOR TRIMS & GARNISHES	New	200.00	100.00
4	REMOVE AND REFIT REAR QUARTER GLASS	New	200.00	100.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	1,000.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	1,000.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			3,250.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >