



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1972T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FREEZER BOX SIDE WOODEN BOARD ASSY (SN) (LOCAL REPAIR)	CRACKED	4,500.00	2,000.00
1	FREEZER BOX LOWER STRUCTURE PANEL (SN)	TO REPAIR SEE LABOUR	2,200.00	-
1	REAR MUDGUARD - RH (SN)	NOT NECESSARY	350.00	-
1	REAR SIDE FRIDGE DOOR FRAME LH (ALUMINIUM CLADDING - HORIZONTAL) (SN)	SERVICEABLE	680.00	-
			7,730.00	2,000.00
<u>LABOUR</u>				
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	150.00	-
	PANEL BEATING.	NOT NECESSARY	1,500.00	-
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	600.00
			3,110.00	600.00
GRAND TOTAL			10,840.00	2,600.00
RECOMMENDED COST OF REPAIRS				2,600.00

Report Ref No. CS/FCI22004815/Uvy3e2

MARKET VALUE: \$26,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,773.00=NETT VALUE: \$17,227.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.