



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBN 8226R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER LH (WCP)	TO REPAIR SEE LABOUR	240.00	-
1	FRONT FENDER INNER SHIELD LH (WCP)	DEFORMED / TORN	105.00	105.00
2	FRONT FENDER BRACKET LH @ \$20.00 (WCP)	NOT NECESSARY	40.00	-
1	FRONT SHOCK ABSORBER LH (WCP)	NOT NECESSARY	280.00	-
1	FRONT SHOCK ABSORBER LH TOP MOUNTING (WCP)	NOT NECESSARY	90.00	-
1	FRONT KNUCKLE ARM LH (WCP)	NOT NECESSARY	268.00	-
1	FRONT KNUCKLE BEARING LH (WCP)	NOT NECESSARY	175.00	-
1	FRONT LOWER ARM (WCP)	NOT NECESSARY	320.00	-
1	ANTI-ROLL BAR ENDLINK LH (WCP)	NOT NECESSARY	55.00	-
1	FRONT BUMPER (WCP)	DEEP CUT	360.00	360.00
2	FRONT BUMPER RETAINER LH/RH @ \$25.00 (WCP)	N/S BENT	50.00	25.00
1	FRONT BUMPER LOWER GARNISH (WCP)	NOT NECESSARY	245.00	-
1	FRONT BUMPER VERTICAL GARNISH LH (WCP)	NOT NECESSARY	148.00	-
1	FRONT HEADLAMP ASSEMBLY LH (WCP)	CRACKED	2,800.00	2,800.00
1	FRONT HEADLAMP LOWER BRACKETS LH (WCP)	NOT NECESSARY	40.00	-
1	FRONT HEADLAMP MOULDINGS LH (WCP)	NOT NECESSARY	120.00	-
	COST PLUS 15%		800.40	493.50
			6,136.40	3,783.50
<b><u>SPECIAL NETT ITEMS</u></b>				
10	FRONT BUMPER CLIPS @ \$3.00 (SN)	NECESSARY	30.00	30.00
1	FRONT TYRE LH (SN)	NOT NECESSARY	280.00	-
1	FRONT WHEEL RIM LH (SN)	NOT NECESSARY	450.00	-
			760.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL WIRING SYSTEMS.		80.00	20.00
	TO CONDUCT COMPUTERIZED 4-WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE FRONT LH SHOCK ABSORBER, KNUCKLE ARM, BEARING, ENDLINK, ETC.	NOT NECESSARY	160.00	-
	TO DIAGNOSE, ERASE FAULT MEMORY CODE AFTER REPAIR.	NOT NECESSARY	80.00	-

Report Ref No. CS/LPC22004818/Uqy3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING & ETC.		850.00	400.00
	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		800.00	300.00
			2,090.00	720.00
<b>GRAND TOTAL</b>			<b>8,986.40</b>	<b>4,533.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/LPC22004818/Uqy3s2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.