

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004823/UEA3Q2**Date:** 05/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700020636
Claimant Vehicle No :	SKE8211Z	Insured Vehicle No :	SLQ1058X
Date of Loss:	21/05/2022	Nature of Claim:	TP
		Claim No:	8151973351SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE8211Z	Engine No:	CZE823499
Make & Model:	AUDI A3, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZ8V7JA144087
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	39406 km
Colour:	Yellow		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,157.00	12,388.60	19,768.40	61.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,660.00	2,690.00	50.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,507.00	15,048.60	22,458.40	59.88
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	37,507.00	12,000.00	25,507.00	68.01
+ GST 7.00/7.00% (S\$)	2,625.49	840.00	1,785.49	68.01
Nett Amount (S\$)	40,132.49	12,840.00	27,292.49	68.01
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,322.00		
Global Sum Settlement (S\$)		13,300.00		

INSPECTION

Date of Assignment:	23/05/2022	
Date Inspected:	23/05/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	2,665.00 F	*- FL
2	1		*TAILGATE REAR LOGO	Not Necessary	105.00 F	*- FL
3	1		*TAILGATE A3 EMBLEM	Not Necessary	82.00 F	*- FL
4	1		*TAILGATE TFSI EMBLEM	Not Necessary	85.00 F	*- FL
5	1		*TAILGATE INNER LOCK	Not Necessary	421.00 F	*- FL
6	2		*TAILGATE REFLECTORS	Not Necessary	1,399.00 F	*- FL
7	1		*TAILGATE WEATHERSTRIP	Serviceable	322.00 F	*- FL
8	1		*REAR BUMPER	Deformed / Torn	2,245.00 F	*1,866.21 FL
9	1		*REAR BUMPER LOWER	Deformed	981.00 F	*385.50 FL
10	2		*REAR BUMPER REFLECTORS	Not Necessary	230.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	180.00 F	*- FL
12	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	720.00 F	*360.00 FL
13	1		*REAR BUMPER BEAM	Bent	715.00 F	*565.00 FL
14	1		*REAR BUMPER SPONGE	Not fitted	185.00 F	*- FL
15	1		*REAR BUMPER TOP RETAINER	Cracked	285.00 F	*205.40 FL
16	1		*REAR END PANEL	Repair	1,122.00 F	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	305.00 F	*- FL
18	2		*TAILLAMPS	Not Necessary	1,960.00 F	*- FL
19	1		*BONNET	Repair	3,320.00 F	*- FL
20	1		*BONNET LOCK	Not Necessary	290.00 F	*- FL
21	1		*FRONT BUMPER	Deformed / Torn	2,146.00 F	*1,920.35 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	855.00 F	*605.00 FL
23	1		*FRONT BUMPER SPONGE	Torn	252.00 F	*168.50 FL
24	1		*FRONT BUMPER INNER RETAINER	Torn	310.00 F	*172.30 FL
25	1		*FRONT GRILLE ASSY	Cracked	885.00 F	*765.00 FL
26	1		*FRONT SUPPORT PANEL	Cracked	780.00 F	*680.00 FL
27	2		*FRONT AIR GUIDES	Serviceable	150.00 F	*- FL
28	1		*CONDENSER	Not Necessary	882.00 F	*- FL
29	1		*RADIATOR	Not Necessary	950.00 F	*- FL
30	2		*HEADLAMPS	Cracked	5,620.00 F	*5,200.00 FL
31	2		*FRONT FENDERS	Repair	1,510.00 F	*- FL
32	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
33	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
35	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,157.00	13,033.26
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	644.66
Total Parts (\$)	32,157.00	12,388.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	180.00	50.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
7	TO SPRAY RUST PROOFING	New	120.00	0.00
8	TO REFILL AIR CON GAS	New	120.00	100.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	1,100.00
10	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,250.00
Gross Labour Cost (\$\$)			5,350.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >