

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22004829/UPA3Q2**Date:** 30/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLX1342M **Insured Vehicle No :** SMP7992C

Date of Loss: 14/05/2022 Nature of Claim: TP Claim No: MFL2022D0002582

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX1342M**

Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11030338

Reg. Date: 16/03/2018 (Man. Year: 2017) Chassis No: JHMGK3850JX210722

Colour: Yellow Odometer: 45273 km

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,055.39	1,734.03	321.36	15.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,980.00	6,351.50	3,628.50	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,035.39	8,085.53	3,949.86	32.82
+ GST 7.00/7.00% (S\$)	842.48	565.99	276.49	32.82
Nett Amount (S\$)	12,877.87	8,651.52	4,226.35	32.82
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
Nett Liability (S\$)		9,400.52		

INSPECTION

Date of Assignment: 23/05/2022

Date Inspected: 31/05/2022

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2022)
Parts:	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1342M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ,RR BUMPER	Distorted	378.75 FS	*378.75 FS
2	1		*GARNISH ,RR BUMPER	Grazed	30.60 FS	*30.60 FS
3	1		*COVER .RR.EXPI FIN	Not Necessary	7.42 FS	*- FS
4	1		*SPACER ,R.RR BUMPER SIDE	Not Necessary	13.50 FS	*- FS
5	1		*SPACER ,L.RR BUMPER SIDE	Bent	13.50 FS	*13.50 FS
6	1		*CLIP BUMPER	Necessary	1.72 FS	*1.72 FS
7	1		*LINING ASSY ,RR PANEL	Twisted	45.60 FS	*45.60 FS
8	1		*PANEL COMPRR	Badly Dented	256.20 FS	*256.20 FS
9	1		*TAIL GATE COMP	Badly Dented	584.40 FS	*584.40 FS
10	1		*WEATHERSTRIP TAILGATE	Twisted	69.22 FS	*69.22 FS
11	1		*LOCK ASSY ,TAILGATE	Serviceable	67.57 FS	*- FS
12	1		*LINING ASSYTAILGATE LOWER	Deformed / Cracked	45.97 FS	*45.97 FS
13	1		*TAILLIGHT ASSY,R	Not Necessary	191.70 FS	*- FS
14	1		*TAILLIGHT ASSY,L	Cracked	191.70 FS	*191.70 FS
15	1		*RUBBER CWINDSHIELD DAMPER	Necessary	9.15 FS	*9.15 FS
16	2		*RUBBERWINDSHIELD DAMPER	Necessary	11.10 FS	*11.10 FS
17	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
18	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
19	1		*EMBLEMH	Serviceable	8.02 FS	*- FS
20	2		*NUT PUSH 3MM	Not Necessary	3.15 FS	*- FS
21	1		*EMBLEMRR	Necessary	9.30 FS	*9.30 FS
22	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,055.39** **1,734.03**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	108.00
2	BODY JOINT SEALANT	New	100.00	100.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	0.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	292.50
7	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	315.00
8	REMOVE & INSTALL RR WINDSCREEN	New	650.00	405.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	550.00	405.00
10	KNOCK FLOOR ,CUT RR PANEL STRAIGHTEN FENDERS ALIG	New	3,500.00	2,340.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,300.00	2,106.00
Gross Labour Cost (\$\$)			9,980.00	6,351.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >