

HDA

CO. SDN. BHD.

(The Oriental Holdings Berhad)

Repair

3838

Website: www.honda.com.sg

Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

: INDIA INTERNATIONAL INSURANCE PTE  
 64 CECIL STREET  
 #04-00 & #05-00 IOB BUILDING  
 SINGAPORE 049711  
 Registration No : SLX1342M  
 Chassis No : JHMGK3850JX210722  
 Model : JAZZ 1.3LXR CVT 18YM (EURO 6)  
 Owner's Name : TAN SOON KEONG  
 Ins Policy No. :  
 Date of Accident : 14/5/2022

Document No. : SQT22001352 Page 1  
 Date : 17. May 2022  
 Customer No. : WZI007  
 Svc Advisor : SUHELMI  
 Engine No : L13B11030338  
 Date | Time : 17. May 2022 9:25:45 AM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

| Item            | Description                                                                                                                                                                                                | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: TAN SOON KEONG<br>OWNER INSURER: SINGAPORE LIFE<br>ACC DATE: 14/05/2022<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: INDIA INTERNATIONAL<br>TP VEH: SMP7992C |     |            |        |        |               |                  |
| 04715-T5A-J50ZZ | FACE,RR.BUMPER <i>Dis</i>                                                                                                                                                                                  | 1   | 505.00     | 25     | 378.75 | 26.51         | 405.26           |
| 71505-T5A-J50   | GARNISH,RR.BUMPER <i>grab</i>                                                                                                                                                                              | 1   | 40.80      | 25     | 30.60  | 2.14          | 32.74            |
| 71503-T5A-J50   | COVER,RR.EXPI FIN <i>na</i>                                                                                                                                                                                | 1   | 9.90       | 25     | 7.42   | 0.52          | 7.94             |
| 71593-T5A-J50   | SPACER,R.RR.BUMPER SIDE <i>11</i>                                                                                                                                                                          | 1   | 18.00      | 25     | 13.50  | 0.95          | 14.45            |
| 71598-T5A-J50   | SPACER,L.RR.BUMPER SIDE <i>Surf</i>                                                                                                                                                                        | 1   | 18.00      | 25     | 13.50  | 0.95          | 14.45            |
| 91505-TM8-003   | CLIP,BUMPER <i>new</i>                                                                                                                                                                                     | 1   | 2.30       | 25     | 1.72   | 0.12          | 1.84             |
| 84640-T5A-003ZA | LINING ASSY,RR.PANEL <i>new</i>                                                                                                                                                                            | 1   | 60.80      | 25     | 45.60  | 3.19          | 48.79            |
| 66100-TAR-T00ZZ | PANEL COMPRR. <i>body</i>                                                                                                                                                                                  | 1   | 341.60     | 25     | 256.20 | 17.93         | 274.13           |
| 68100-T5A-U10ZZ | TAIL GATE COMP <i>body</i>                                                                                                                                                                                 | 1   | 779.20     | 25     | 584.40 | 40.91         | 625.31           |
| 74440-T5A-003   | WEATHERSTRIPTAILGATE <i>new</i>                                                                                                                                                                            | 1   | 92.30      | 25     | 69.22  | 4.85          | 74.07            |
| 74801-T5S-K01   | LOCK ASSY,TAILGATE <i>Sur</i>                                                                                                                                                                              | 1   | 90.10      | 25     | 67.57  | 4.73          | 72.30            |
| 84440-T5A-J02ZA | LINING ASSYTAILGATE LOWER <i>De/Cro</i>                                                                                                                                                                    | 1   | 61.30      | 25     | 45.97  | 3.22          | 49.19            |
| 33500-T5A-J02   | TAILLIGHT ASSY,R. <i>11</i>                                                                                                                                                                                | 1   | 255.60     | 25     | 191.70 | 13.42         | 205.12           |
| 33550-T5A-J02   | TAILLIGHT ASSYL. <i>one</i>                                                                                                                                                                                | 1   | 255.60     | 25     | 191.70 | 13.42         | 205.12           |
| 73127-TY0-000   | RUBBER CWINDSHIELD DAMPER <i>new</i>                                                                                                                                                                       | 1   | 12.20      | 25     | 9.15   | 0.64          | 9.79             |
| 73214-T5A-013   | RUBBERWINDSHIELD DAMPER <i>new</i>                                                                                                                                                                         | 2   | 7.40       | 25     | 11.10  | 0.78          | 11.88            |
| 73226-SZW-000   | DAMPERSTD 5X5 <i>new</i>                                                                                                                                                                                   | 1   | 9.10       | 25     | 6.82   | 0.48          | 7.30             |
| BO-WS-SEALANT   | WINDSCREEN SEALANT (N) <i>new</i>                                                                                                                                                                          | 1   | 60.00      |        | 60.00  | 4.20          | 64.20            |
| 75701-T5A-000   | EMBLEMH <i>Sur</i>                                                                                                                                                                                         | 1   | 10.70      | 25     | 8.02   | 0.56          | 8.58             |

Printed on 17/5/2022 10:12:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



HONDA

KOH CO. SDN. BHD.

the Oriental Holdings Berhad)

Repair

3838

Website: www.honda.com.sg

Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

er : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711  
Registration No : SLX1342M  
Chassis No : JHMGK3850JX210722  
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)  
Owner's Name : TAN SOON KEONG  
Ins Policy No. :  
Date of Accident : 14/5/2022

Document No. : SQT22001352 Page 2  
Date : 17. May 2022  
Customer No. : WZI007  
Svc Advisor : SUHELMI  
Engine No : L13B11030338  
Date | Time : 17. May 2022 9:25:45 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

| Item          | Description                                        | Qty | Unit Price | Disc % | Amount   | 0% GST Amount | Amount incld GST |
|---------------|----------------------------------------------------|-----|------------|--------|----------|---------------|------------------|
| 90301-ST0-003 | NUT,PUSH 3MM                                       | 2   | 2.10       | 25     | 3.15     | 0.22          | 3.37             |
| 75722-T5L-T01 | EMBLEMRR.                                          | 1   | 12.40      | 25     | 9.30     | 0.65          | 9.95             |
| Sum Item      |                                                    |     |            |        | 2005.39  | 140.39        | 2,145.78         |
| BOSUN         | SUNDRIES                                           | 1   | 50.00      | 20     | 50.00    | 3.50          | 53.50            |
| BML02I        | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER      | 1   | 180.00     | 120    | 180.00   | 12.60         | 192.60           |
| BOJSE         | BODY JOINT SEALANT.                                | 1   | 100.00     | ✓      | 100.00   | 7.00          | 107.00           |
| BOBC          | BODY UNDERSIDE COATING (N)                         | 1   | 100.00     | ✓      | 100.00   | 7.00          | 107.00           |
| BP00R         | APPLY BODY UNDERSIDE COATING (N).                  | 1   | 250.00     | 180    | 250.00   | 17.50         | 267.50           |
| BC012R        | RESET VEHICLE SMART ENTRY SYSTEM                   | 1   | 450.00     | X      | 450.00   | 31.50         | 481.50           |
| BMI03D        | REMOVE & INSTALL REAR COMPARTMENT LININGS          | 1   | 450.00     | 325    | 450.00   | 31.50         | 481.50           |
| BC011R        | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA        | 1   | 450.00     | 350    | 450.00   | 31.50         | 481.50           |
| BG02D         | REMOVE & INSTALL RR. WINDSCREEN.(N)                | 1   | 650.00     | 450    | 650.00   | 45.50         | 695.50           |
| BKTG02R       | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &  | 1   | 550.00     | 450    | 550.00   | 38.50         | 588.50           |
| BKRP02B       | KNOCK FLOOR, CUT RR PANEL.STRAIGHTEN FENDERS. ALIG | 1   | 3500.00    | 2600   | 3500.00  | 245.00        | 3745.00          |
| BP06R         | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1   | 3300.00    | 2340   | 3300.00  | 231.00        | 3531.00          |
| Sum Labor     |                                                    |     |            |        | 10030.00 | 702.10        | 10,732.10        |

Survey By

Date &amp; Time

Excess

Status

Signature

Marcus Hill  
31/05/22 @ P.15am  
Not Attached  
Take photo before painting.  
90096608 7 days

Total Amount 12,035.39 842.49 12,877.88

Total (Inclusive of GST) 12,877.88

Printed on 17/5/2022 10:12:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: