



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8079X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER REAR BUMPER (CONSISTENT)	DEFORMED	503.04	503.04
10	BUMPER PIECE (CONSISTENT)	NECESSARY	22.00	22.00
1	GUARD -REAR BUMPER CENTER (CONSISTENT)	DEFORMED	654.96	654.96
1	GARNISH S.ASSY BACK DOOR (CONSISTENT)	CRACKED	1,054.71	1,054.71
1	PLATE -BACK DOOR NAME (HYB) (CONSISTENT)	NECESSARY	62.14	62.14
1	PLATE -BACK DOOR NAME (PRI) (CONSISTENT)	NECESSARY	62.14	62.14
	LESS 25% DISCOUNT		-589.75	-589.75
			1,769.24	1,769.24
SPECIAL NETT ITEMS				
1	REAR BOOT 65521111 CTPL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR BONNET APP TAXI BOOK (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BOOT LOGO CTPL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	ADVERTISEMENT STICKER -BUMPER (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	ADVERTISEMENT STICKER -FENDER (SN) (CONSISTENT)	NECESSARY	200.00	200.00
			350.00	350.00
LABOUR				
	PANEL BEATING.		800.00	350.00
	SPRAYPAINT CHARGE.		600.00	500.00
	REMOVE /REFIX REVERSE SENSOR .		50.00	30.00
			1,450.00	880.00
GRAND TOTAL			3,569.24	2,999.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC4/ASM22004831/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.