



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6903U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	FRONT O/S & N/S HEAD LAMP @\$1028.00 (CONSISTENT)	O/S NOT NECESSARY / N/S CRACKED	2,056.00	1,028.00
1	BONNET GRILLE (CONSISTENT)	NOT NECESSARY	385.00	-
1	FRONT BUMPER (CONSISTENT)	DENTED	531.00	531.00
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	44.00	44.00
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00 (CONSISTENT)	DENTED	32.00	32.00
1	FRONT BUMPER N/S UPPER BRACKET (CONSISTENT)	NOT NECESSARY	16.00	-
1	FRONT BUMPER N/S SUPPORT BRACKET (CONSISTENT)	NOT NECESSARY	16.00	-
1	FRONT BUMPER O/S PROTECTOR (CONSISTENT)	CUT	51.00	51.00
1	FRONT BUMPER O/S FOG LIGHT COVER (CONSISTENT)	CUT	66.00	66.00
1	FRONT DOOR LH (NPA)(CONSISTENT)	NOT NECESSARY	-	-
1	FRONT N/S WHEEL COVER (CONSISTENT)	NOT NECESSARY	116.00	-
1	FRONT N/S FENDER (CONSISTENT)	BENT	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD (CONSISTENT)	TORN	120.00	120.00
	LESS 10% DISCOUNT		-381.70	-225.60
			3,435.30	2,030.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	48.00	30.00
1	FRONT N/S FENDER STICKER (SN)(CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	28.00	28.00
1	SUNDRY (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
			156.00	88.00
<b><u>LABOUR</u></b>				
	TO FOCUS AND ADJUST FRONT N/S & O/S HEAD LAMPS.		60.00	30.00
	TOWING FEE.		50.00	50.00
	TO CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-

Report Ref No. CC4/ASM22004832/Tga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.		800.00	500.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,BONNET ,FRONT O/S FENDER.		900.00	800.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
			1,970.00	1,410.00
<b>GRAND TOTAL</b>			<b>5,561.30</b>	<b>3,528.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,800.00</b>

Report Ref No. CC4/ASM22004832/Tga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.