

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004835/UPA3Q2**Date:** 27/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800105332
Claimant Vehicle No :	GBE6144D	Insured Vehicle No :	SMD7843M
Date of Loss:	15/05/2022	Nature of Claim:	TP
		Claim No:	8988676040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6144D	Engine No:	YD25386323A
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)	Chassis No:	JN1MC2E26Z0005644
Reg. Date:	23/01/2016 (Man. Year: 2015)	Odometer:	112206 km
Colour:	Brown		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,579.10	869.79	3,709.31	81.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,020.00	1,350.00	56.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,949.10	1,889.79	5,059.31	72.81
Approved Total (Overridden) (\$\$)		1,500.00		
Nett Amount (\$\$)	6,949.10	1,500.00	5,449.10	78.41
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	27/05/2022		
Date Inspected:	27/05/2022	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Repair	1,916.00 F	*- FL
2	1		*REAR BOOT COVER EMBLEM (LOGO)	Not Necessary	95.90 F	*- FL
3	1		*REAR BOOT COVER EMBLEM (NV 350)	Necessary	110.00 F	*110.00 FL
4	1		*REAR WINDSCREEN GLASS	Not Necessary	1,000.00 F	*- FL
5	1		*REAR END PANEL	Repair	286.10 F	*- FL
6	1		*REAR BUMPER FASCIA	Dented / Deformed	573.10 F	*573.10 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*SET REAR BUMPER SENSOR	Shorted	380.00 FS	*200.00 FS
9	1		*REAR BOOT COVER STICKER (70KM/H)	Necessary	28.00 FS	*10.00 FS
10	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
11	1		*REAR WINDSCREEN SEALER	Not Necessary	80.00 FS	*- FS
					Sub Total (\$\$)	4,579.10 943.10
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 73.31
					Total Parts (\$\$)	4,579.10 869.79

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT ,RENEW ,KNOCKING & WELDING REAR BOOT COVER ,REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY	New	980.00	450.00
2	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	50.00
3	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
4	TUFF-KOTE ON DAMAGE PARTS	New	80.00	0.00
5	SPRAY PAINTING ON DAMAGE PARTS	New	1,080.00	500.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	30.00	20.00
Gross Labour Cost (S\$)			2,370.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >