



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 339K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR LAMP (BRAKE LAMP ASSY) (CONSISTENT)	BROKEN	240.00	240.00
2	REAR SIGNAL LAMP @\$58.00 (CONSISTENT)	BROKEN	116.00	116.00
2	REAR REFLECTOR @\$28.00 (CONSISTENT)	NOT NECESSARY	56.00	-
1	REAR LAMP GARNISH (CONSISTENT)	BROKEN	99.00	99.00
1	REAR LAMP TOP COVER (CONSISTENT)	NOT NECESSARY	178.00	-
2	REAR LAMP BOTTOM COVER @\$198.00 (CONSISTENT)	NOT NECESSARY	396.00	-
1	REAR FENDER (CONSISTENT)	BROKEN	148.00	148.00
1	REAR FENDER DUST GARNISH (CONSISTENT)	BROKEN	180.00	180.00
2	REAR RS150R EMBLEM @\$45.00 (CONSISTENT)	NECESSARY	90.00	90.00
1	REAR TOOLBOX HOLDER (CONSISTENT)	CUT	185.00	185.00
2	REAR FOOT REST @\$60.00 (CONSISTENT)	O/S NOT NECESSARY / N/S CUT	120.00	60.00
2	CENTRE FOOT REST @\$63.00 (CONSISTENT)	O/S NOT NECESSARY / N/S BENT	126.00	63.00
1	FOOT GEAR LEVER (CONSISTENT)	BENT	98.00	98.00
1	EXHAUST PIPE ASSY (CONSISTENT)	NOT NECESSARY	480.00	-
1	EXHAUST GARNISH (CONSISTENT)	CUT	120.00	120.00
1	TYRE (CONSISTENT)	NOT NECESSARY	280.00	-
1	SPORT RIM (CONSISTENT)	NOT NECESSARY	410.00	-
1	REAR WHEEL SHAFT (CONSISTENT)	NOT NECESSARY	120.00	-
1	SET REAR SIDE FAIRING (CONSISTENT)	CUT	495.00	495.00
1	SET REAR SIDE FAIRING STICKER (CONSISTENT)	NECESSARY	160.00	160.00
1	SET REAR SIDE FAIRING HONDA STICKER (CONSISTENT)	NOT NECESSARY	90.00	-
1	CLUTCH LEVER (CONSISTENT)	CUT	110.00	110.00
1	SIDE MIRROR LH (CONSISTENT)	BROKEN	98.00	98.00
1	REAR CENTRE REFLECTOR (CONSISTENT) (ADDITIONAL)	BROKEN	28.00	28.00
1	REAR SIGNAL HOLDER (CONSISTENT) (ADDITIONAL)	BROKEN	90.00	90.00
1	REAR LAMP HOLDER (CONSISTENT) (ADDITIONAL)	BROKEN	85.00	85.00

Report Ref No. CS/ASM22004844/Dvce2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LAMP HOLDER RUBBER (CONSISTENT) (ADDITIONAL)	NECESSARY	59.00	59.00
	LESS 10% DISCOUNT		-	-252.40
			4,657.00	2,271.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR TOOLBOX (SN) (CONSISTENT)	DISLODGE	399.00	180.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT / CUT	30.00	15.00
			429.00	195.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIT LAMP AND CHECK WIRE.		80.00	20.00
	TO REMOVE & REFIT RENEW REAR TYRE & RIM.		60.00	15.00
	TO REPAIR & RENEW ALL ACCIDENT AFEFCTED AREA.		480.00	250.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED DAMAGED PARTS.		400.00	150.00
			1,020.00	435.00
<b>GRAND TOTAL</b>			<b>6,106.00</b>	<b>2,901.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,300.00</b>

Report Ref No. CS/ASM22004844/Dvce2

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.