6/6/22, 11:32 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22004849/UTY3N2

Date: 06/06/2022

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP316720

Claimant Vehicle CN005000 Processor

No: SNC3533C Insured Vehicle No: SCA9300J

Date of Loss: 22/05/2022 Nature of Claim: TP Claim No: MPC03442/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNC3533C

 Make & Model:
 KIA FORTE K3, 1.6 (A)
 Engine No:
 G4FGHH691472

 Reg. Date:
 17/05/2018 (Man. Year: 2017)
 Chassis No:
 KNAFJ411MJ5761385

Colour: Grey Odometer: 106460 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,232.00	4,660.40	5,571.60	54.45
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,010.00	1,400.00	1,610.00	53.49
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,242.00	6,060.40	7,181.60	54.23
	Approved Total (Overridden) (S\$)		4,800.00		
	(S\$)	13,242.00	4,800.00	8,442.00	63.75
	+ GST 7.00/7.00% (S\$)	926.94	336.00	590.94	63.75
	Nett Amount (S\$)	14,168.94	5,136.00	9,032.94	63.75

INSPECTION

Date Inspected:

Date of Assignment: 23/05/2022

Fastech Auto Pte Ltd (HQ)
23/05/2022 Inspected At: 1 Kaki Bukit Ave 6, #01-46/

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2022)

Parts: 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC3533C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	966.00 F	*633.00 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	75.00 F	*45.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	381.00 F	*-FL
5	1		*FRONT BUMPER KIA LOGO	Necessary	102.00 F	*58.00 FL
6	1		*HEADLAMP N/S	Cracked	1,998.00 F	*810.00 FL
7	1		*FRONT SUPPORT PANEL	Cracked	945.00 F	*675.00 FL
8	1		*FRONT FENDER N/S	Dented	755.00 F	*419.00 FL
9	1		*FRONT FENDER INNER SHIELD N/S	Deformed	282.00 F	*180.00 FL
10	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
11	1		*FRONT LOWER ARM N/S	Bent	698.00 F	*380.00 FL
12	1		*FRONT SHOCK ABSORBER N/S	Bent	590.00 F	*313.00 FL
13	1		*FRONT KNUCKLE ARM N/S	Bent	545.00 F	*393.00 FL
14	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	290.00 F	*150.00 FL
15	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,105.00 F	*- FL
16	1		*FRONT SPORT RIM N/S	Cut/Warped	1,200.00 FS	*800.00 FS
17	1		*FRONT TYRE N/S (60%)	Cut	200.00 FS	*120.00 FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.			
				Sub Total (S\$)	10,232.00	5,076.00
			- List Item Discount on L Ite	ms 0.00/10.00% (S\$)	0.00	415.60
				Total Parts (S\$)	10,232.00	4,660.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO RESET & DIAGNOSTIC SYSTEM	New	180.00	50.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
5	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	120.00
6	TO SPRAY RUST PROOFING	New	80.00	30.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,280.00	400.00
	Gro	oss Labour Cost (S\$)	3,010.00	1,400.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >