



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CS3/ASM22004850/Vqcm4
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	19/07/2022
ATTN: ANG YVONNE		Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJJ 1824L	Veh. Inspected	SLA 5645J
Policy No.	GA548163	Coverage (\$)	0.00
Claim No.	S2M041OL	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	23/05/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ 1.5	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMGK5850GX201981	Colour	SILVER
Odometer	100396 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	6 mm
L/H Front Tyre	185/55 R16	DUNLOP	6 mm
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	14/05/2022	Inspection Date	23/05/2022
Survey held at	KNW CAR SPRAY PTE LTD BLK 13 DEFU LANE 10 #01-432 SINGAPORE 539194		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	