

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III22004852/EVY3E2

**Date:** 06/07/2022

### REFERENCE

Insured/Claimant: LENG AIK ENGINEERING PTE LTD Policy No: D20MCV0004095\_01  
Date of Loss: 19/05/2022 Nature of Claim: OD Claim No: MCV2022D0002603

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP2418K**  
Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M) Engine No: N04CUS27068  
Reg. Date: 22/04/2016 (Man. Year: 2016) Chassis No: JHHUCS3H50K016816  
Colour: White Odometer: 390783 km  
Engine Capacity: 4009 cc  
Market Value/New Car Price: S\$49,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm  
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,147.65	5,040.79	5,106.86	50.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,510.00	1,680.00	52.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,337.65</b>	<b>6,550.79</b>	<b>6,786.86</b>	<b>50.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00
<b>(S\$)</b>	12,587.65	4,050.00	8,537.65	67.83
<b>+ GST 7.00/7.00% (S\$)</b>	881.14	283.50	597.64	67.83
<b>Nett Amount (S\$)</b>	<b>13,468.79</b>	<b>4,333.50</b>	<b>9,135.29</b>	<b>67.83</b>

### INSPECTION

Date of Assignment: 23/05/2022

Date Inspected: 24/05/2022 Inspected At:

V-Tech Auto Service (HQ)  
No.1 Soon Lee Street, #06-04 Pioneer Center  
Singapore 627605

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Jul 2022)	
<b>Parts:</b>	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP2418K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	1,148.10 F	*1,148.10 FL
2	1		*FRONT PANEL 300 STICKER	Necessary	45.00 F	*45.00 FL
3	1		*FRONT PANEL HINO STICKER	Necessary	50.00 F	*50.00 FL
4	1		*FRONT INNER PANEL	Repair	887.15 F	*- FL
5	1		*HEAD LAMP L/R	N/S Cut	1,220.00 F	*610.00 FL
6	1		*FRONT CENTRE GRILLE ASSY	Broken	542.20 F	*542.20 FL
7	1		*FRONT CENTRE GRILLE ASSY LOGO	Missing	56.00 F	*56.00 FL
8	1		*AIRCON COOLING PIPE	Not Necessary	340.00 F	*- FL
9	1		*AIRCON DISCHARGE PIPE	Bent	550.00 F	*550.00 FL
10	1		*AIRCON SUCTION PIPE	Bent	410.00 F	*410.00 FL
11	1		*AIRCON DRYER UNIT	Not Necessary	118.00 F	*- FL
12	1		*AIRCON BLOWER UNIT	Not Necessary	893.00 F	*- FL
13	1		*AIRCON EVAPORATOR COIL	Not Necessary	871.20 F	*- FL
14	1		*FRONT BUMPER ASSY	Dented	981.80 F	*981.80 FL
15	2		*FRONT BUMPER BRACKET L/R	Not Necessary	240.20 F	*- FL
16	1		*FRONT BUMPER CENTRE INNER BEAM	Dented	230.00 F	*230.00 FL
17	2		*FRONT BUMPER FOG LAMP L/R	Not Necessary	420.00 F	*- FL
18	1		*FRONT PANEL LENG AIK STICKER	Necessary	240.00 FS	*100.00 FS
19	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*15.00 FS
20	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
21	2		*AIR-CON COOLING PIPE (Supplementary)	Bent	680.00 F	*680.00 FL
22	2		*AIR-CON COOLING PIPE BRACKET (Supplementary)	Bent	140.00 F	*140.00 FL
23	1		*FRONT NO PLATE (Supplementary)	Bent	30.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,147.65</b>	<b>5,588.10</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	547.31
<b>Total Parts (\$\$)</b>	<b>10,147.65</b>	<b>5,040.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING	New	120.00	30.00
2	TO REMOVE, CHANGE DASHBOARD FASCIA AND TRANSFER WHERE NECESSARY	New	350.00	0.00
3	TO REMOVE, REPLACED AIR CON PIPING, CHECK EVAPORATOR UNIT, AIRCON BLOWER MOTOR AND ETC TO VACUUM SYSTEM AND TOP UP GAS	New	200.00	150.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE , BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,190.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >