

ASS. REC. BY:

REF: ASM/ 22004853/Knc

*Kenneth*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop nvs Hc Auto

of 378W

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: Q37K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBE 7843M Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make: NIS NV200 c.c. 1461

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 191114 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VSKYBAM 202 0124285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Westlake

R: Falken 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 20/5/22 D.O.I. 24/5/2022

Survey held at 8/15/22 10.40am

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2/15/22

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>GIA not ready</u>
<u>03</u>	<u>L/Rmp @ 11,200/r (Red. #13910.12, 55%)</u>

Date/Time, File Pass to?

: Prell. Report  
 : Final Report

Days Of Repair: 16

Resurvey No. of Trip: 2

Survey Fee:

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech Invs (\$ )  
 : Weekend (\$ )

Transportation
S + RS
Fees
Others
TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST reg. No: 20082 0153N

*Not Authorized*  
*11 hrs @ 11,200/hr*  
*Recovery After Paint*  
*16 days*

Date : 23 / 05 / 2022

## ESTIMATE COSTS OF REPAIR

### M/s Hwa Hing Trading Pte Ltd

C/o 160 Sin Ming Drive

# 05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : GBE 7843 M - Nissan NV200 1.5 MT

Accident date : 20 / 05 / 2022

Quantity	Descriptions	Amount ( S\$ )
----------	--------------	----------------

1	1 pc front bumper	\$ <i>Bu</i> 563.50 n ✓
2	1 pc front bumper reinforcement	\$ <i>R</i> 591.90 n X
3	2 pcs front bumper side retainer 1 @ 35.20	<i>n/s</i> \$ 70.40 n ✓
4	1 pc front bumper sponge <i>186</i>	\$ <i>cm</i> 308.80 n ✓
5	2 pcs head lamp lower garnish 1 @ 348.60 <i>olsm X</i>	<i>n/s</i> \$ <i>cm</i> 697.20 n ✓ <i>+ 2329.80</i>
6	2 pcs front fender 1 @ 548.80	\$ <i>R</i> 1,097.60 n X
7	1 pc front bumper lower cover	\$ <i>su</i> 211.10 n X ✓
8	2 pcs head lamp 1 @ 413.20 nett <i>olsm X</i>	<i>n/s</i> \$ <i>cm</i> 826.40 n ✓
9	1 pc front grille	<i>n/s</i> \$ <i>cm</i> 344.10 n ✓
10	1 pc front grille emblem	\$ <i>cm</i> 52.50 n ✓
11	2 pcs front fender inner garnish 1 @ 204.00 nett	\$ <i>su</i> 408.00 n X
12	1 pc n/s tail gate <i>1450</i>	\$ <i>Bu</i> 1,496.60 n ✓
13	1 pc n/s tail gate rubber (center) <i>231.60</i>	<i>n/s</i> \$ <i>Red</i> 280.00 n <i>500 su 115.80 su</i>
14	1 pc n/s tail gate outer garnish	\$ <i>su</i> 352.00 n X
15	1 pc n/s tail gate inner lock <i>261.90</i>	\$ <i>Red</i> 287.50 n ✓
16	1 pc o/s tail gate <i>1086</i>	\$ <i>Bu</i> 1,102.20 n ✓
17	1 pc o/s tail gate inner lock	\$ <i>Red</i> 287.50 n ✓
18	1 pc rear bumper <i>625</i>	\$ <i>Bu</i> 700.80 n ✓
19	1 pc rear bumper side bracket 1 @ 35.20	\$ <i>su</i> 70.40 n X
20	1 pcs rear bumper sponge	\$ <i>cm</i> 94.00 n ✓
21	2 pcs rear bumper side retainer 1 @ 37.00	<i>n/s</i> \$ <i>Dis</i> 74.00 n ✓
22	2 pcs rear bumper bracket 1 @ 91.70	\$ <i>Dis</i> 183.40 n ✓
23	1 pc rear bumper side beam	<i>n/s</i> \$ 354.50 n X
	Balance C/FD	\$ 10,454.40

# H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST reg. No: 20082 0153N

Balance B/FD ( GBG 3316 J )

\$ 10,454.40

25	1 pc	n/s rear fender	
26	1 pc	n/s rear fender inner garnish	
27	1 pc	n/s rear slicing door rail	
28	1 pc	n/s rear wheel rim	
29	1 pc	n/s rear fender air duct	
30	1 pc	n/s tail gate hinge	
31	1 pc	n/s tail gate rubber	
32	2 pcs	rear bumper reflector	1 @ 61.90
33	6 pcs	end panel top garnish clip	1 @ 5.00
34	1 pc	end panel top garnish	138-10
35	1 pc	tail gate weather strip	

Bu	\$	1,791.60	n	✓
	\$	Pu	120.00	n X
	\$	Su	165.80	n X
	\$	Pu	257.10	n X
	\$	Su	69.10	n X
	\$	Bu	96.50	n ✓
	\$	Del/D:1	88.40	n 309 sn 44-20 sn
	\$	Bu	123.80	n X
	\$	nae	30.00	n ✓
	\$	CM	188.00	n ✓
	\$	CV	221.65	n 506 sn 110-82 sn

\$ 13,606.35

Less 10 %

\$ 1,360.64

\$ 12,245.72

36	2 pcs	front bumper fog lamp	1 @ 320.70 sn
37	1 pc	front no. plate	
38	1 pc	radiator coolant	
39	2 pcs	rear windscreen glass inner seal	
40	2 pcs	rear windscreen glass gum	
41	1 pc	rear spare tyre carrier	
42	1 pc	rear wiper motor	395.40 → 710
43	1 pc	n/s tail gate inner board	321.30 → 710
44	1 pc	o/s tail gate inner board	
45	1 pc	n/s tail gate inner handle	
46	1 pc	n/s tail gate inner checker	
47	1 pc	o/s tail gate inner checker	
48	1 pc	rear end panel (inner)	461.50 } 10%
49	1 pc	rear end panel (outer)	224.80 } 10%
50	1 pc	rear end panel seal	
51	1 set	rear reverse sensor	
52	1 pc	rear no. plate	
53	1 pc	70km/h sticker	
54	1 pc	6 pax sticker	
55	1 pc	fool panel	
56	1 pc	advertisement	
		Balance C/FD	

	\$	Pu	641.40	sn X
	\$	Red	70.00	sn 45 sn
	\$	nu	120.00	sn X
	\$	na	120.00	sn 60 sn
	\$	na	120.00	sn 80 sn
	\$	Bu	189.00	sn 2
	\$	Tu	588.00	sn 2
	\$	Reforms	349.00	sn ✓
	\$	Pu	301.00	sn X
	\$	Su	242.00	sn X
	\$	Pu	188.00	sn X
	\$	Su	188.00	sn X
	\$	Bu	480.00	sn ✓
	\$	Bu	250.00	sn ✓
	\$	na	250.00	sn 30 sn
	\$	scr	350.00	sn 200 sn
	\$	Bu	70.00	sn 45 sn
	\$	na	50.00	sn 15 sn
	\$	na	50.00	sn 15 sn
	\$	K	1,388.00	sn X
	\$	na	1,500.00	sn 750 sn

(Bill)

\$ 19,750.12

# H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST reg. No: 20082 0153N

Balance B/FD ( GBG 3316 J )	\$	19,750.12	
Labour charges	\$	2,500.00	1800
To putty and spray painting	\$	1,800.00	1400
Remove and refix rear n/s & o/s windscreen glass	\$	380.00	120
Refill air con gas	\$	160.00	X
Remove and refix reverse sensor	\$	120.00	50
Re-seal anti rust	\$	200.00	120
To check wheel alignment	\$	80.00	X
To check, replace, repair wiring	\$	120.00	40
	\$	25,110.12	
Plus 7% GST	\$	1,757.71	
Sub-Total	\$	26,867.82	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: