

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004854/VQY3Q2**Date:** 07/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00134722100	
Claimant Vehicle No :	SMA6196U	Insured Vehicle No :	SGD7070Y	
Date of Loss:	19/05/2022	Nature of Claim:	TP	Claim No: SNM22D203476/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6196U		Engine No:	2ZRR956753
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S CVT (A)		Chassis No:	ZVW508037188
Reg. Date:	14/06/2018 (Man. Year: 2016)		Odometer:	251903 km
Colour:	Maroon			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,802.50	2,366.50	3,436.00	59.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,350.00	1,440.00	51.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,592.50	3,716.50	4,876.00	56.75
Approved Total (Overridden) (\$\$)		2,950.00		
Nett Amount (\$\$)	8,592.50	2,950.00	5,642.50	65.67

INSPECTION

Date of Assignment:	23/05/2022	
Date Inspected:	24/05/2022	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMA6196U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	889.00 FL	*458.00 FL
2	1		*REAR BUMPER RETAINER LH	Necessary	59.00 FL	*59.00 FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	59.00 FL	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Dented	382.00 FL	*382.00 FL
5	1		*END PANEL	Repair	582.00 FL	*- FL
6	1		*END PANEL TOP GARNISH	Cut	119.00 FL	*119.00 FL
7	1		*REAR KEYLESS SENSOR	Cut	311.00 FL	*281.00 FL
8	1		*BOOT	Dented	1,258.00 FL	*1,050.00 FL
9	1		*REAR RH FENDER	Repair	2,243.00 FL	*- FL
10	1		*TAILLAMP RH	Cracked	928.00 FL	*433.00 FL
11	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
13	1		*SET REAR REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
14	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
15	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,510.00	3,062.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,707.50	695.50
Total Parts (\$)	5,802.50	2,366.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACED PARTS	New	1,200.00	600.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS	New	100.00	30.00
3	TO REMOVE AND STRAIGHTEN REAR EXHAUST	New	120.00	60.00
4	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR	New	150.00	0.00
5	TO MEASURE DRILL HOLES ON REPLACED REAR BUMPER ,POSITION AND INSTALL REVERSE SENSOR ,CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	New	120.00	30.00
6	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	100.00	30.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REAR BUMPER AND OTHER AFFECTED AREA /PANEL	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,790.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >