

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD			Ref:	CS3/ASM22004858/Rvy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	27/05/2022	
	ATTN: HO WINNIE			Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 916S	Veh. Inspected	k	FY 6980D
	Policy No.	VFX/P2413997	Coverage (\$)		0.00
	Claim No.	S2M0403I	Excess (\$)		0.00
	Assign From	HO WINNIE	Assign Date		23/05/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400SF4J M	c.c		399
	Engine No.	HIDDEN	Year of Reg.		2004
	Chassis No.	NC391054901	Colour		BLACK
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/60Z R17	MICHELIN		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	160/60Z R17	MICHELIN		4 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.				
5.	. General Information				
	Accident Date	30/04/2022	Inspect Date /	Time	25/05/2022 ( 02:44 PM )
	Survey held at M2 GARAGE PTE LTD 61 WOODLANDS INDUSTRIAL PARK E9 #01-17 E9 PREMIUM SINGAPORE 757047				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22004858/Rvy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD Astro Consultant CAE Library of August

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$