

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004861/AQCE2**Date:** 23/11/2022**REFERENCE**

Insured/Claimant:	HONG JYE SHENG	Policy No:	1800137841	
Date of Loss:	09/05/2022	Nature of Claim:	OD	Claim No: 8496495297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8787U		
Make & Model:	AUDI A3 SPORTBACK, 1.4 TFSI (A)	Engine No:	CZE824009
Reg. Date:	11/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V6JA145831
Colour:	Silver	Odometer:	50157 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$97,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,577.00	6,080.80	8,496.20	58.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,042.00	2,960.00	59.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,579.00	8,122.80	11,456.20	58.51
+ GST 7.00/7.00% (S\$)	1,370.53	568.60	801.93	58.51
Nett Amount (S\$)	20,949.53	8,691.40	12,258.13	58.51

INSPECTION

Date of Assignment:	23/05/2022		
Date Inspected:	20/05/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	332.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	318.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,578.00 FS	*- FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
9	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
10	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	210.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	136.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	846.00 FS	*- FS
15	1		*FRONT FENDER-RH	Repair	954.00 FS	*- FS
16	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
17	1		*FRONT FENDER BRACKET-RH	Not Necessary	56.00 FS	*- FS
18	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	68.00 FS	*- FS
19	1		*FRONT FENDER BRACE-RH	Not Necessary	107.00 FS	*- FS
20	8		*FRONT FENDER POP RIVET	Not Necessary	31.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	183.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	60.00 FS	*- FS
23	1		*HEADLIGHT-RH	Cut	5,879.00 FS	*4,364.00 FS
24	1		*LIFT CYLINDER-RH	Not Necessary	156.00 FS	*- FS
25	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE-RH	Not Necessary	28.00 FS	*- FS
27	1		*RADIATOR SEAL-RH OUTER	Not Necessary	9.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	14.00 FS	*- FS
29	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS
30	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **14,577.00** **6,080.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENT.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	2,042.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >