

ASS. REG. BY:

REF:

C72/ 22004863/KC

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 5780/H Yr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toyota Proace c.c. 1797

Colour:

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading:

323560 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZVW 50 8035934

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Colom 195/65R15
R: Atrezzo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

7 mm

L/Bal.

8 mm

L/Bal.

7 mm

D.O.A.

22/5/22

D.O.I.

24/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/5 11:15 AM @ 1150h Com h 3/6/22

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

22/05/2022

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG5780H

1pc	LH side skirt	K	\$ 685.00	X
1pc	rear bumper	487.50	487.50	✓
1pc	rear bumper LH side retainer	R	\$ 181.50	X
1pc	rear bumper LH side garnish	R	\$ 281.50	X
			\$ 1,829.50	
	less 25%		\$ 457.38	
			\$ 1,372.13	
1pc	rear LH rim half cap	2.1/607	s.nett \$ 120.00	✓
	wiring	nn	\$ 50.00	X
	spray painting		\$ 1,200.00	6001
	labour charges		\$ 800.00	3601
	Total		\$ 3,542.13	

Not Withhold
11 Pm @ 1150h
Penny After Paint
3 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: