

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004864/AYA3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070118110
Claimant Vehicle No :	SDM8858Z	Insured Vehicle No :	SKG7722L
Date of Loss:	21/05/2022	Nature of Claim:	TP
		Claim No:	4461902429SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM8858Z	Engine No:	DAX012912
Make & Model:	AUDI Q5, 2.0 (A)	Chassis No:	WAUZZZF3H2048510
Reg. Date:	27/09/2017 (Man. Year: 2017)	Odometer:	42465 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,043.00	4,594.96	33,448.04	87.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,672.00	2,272.00	7,400.00	76.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	47,715.00	6,866.96	40,848.04	85.61
+ GST 7.00/7.00% (S\$)	3,340.05	480.69	2,859.36	85.61
Nett Amount (S\$)	51,055.05	7,347.65	43,707.40	85.61
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,619.65		

INSPECTION

Date of Assignment:	27/05/2022		
Date Inspected:	27/05/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,131.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	338.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP -LH/RH	Not Necessary	84.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	252.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE CENTER	Cracked	161.00 FS	*128.40 FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	850.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	580.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT -LOWER	Not Necessary	246.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	3,910.00 FS	*3,128.00 FS
10	1		*QUATIRO EMBLEM	Not Necessary	111.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	271.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	Not Necessary	1,302.00 FS	*- FS
13	2		*FRONT BUMPER END CAP -LH/RH	Not Necessary	206.00 FS	*- FS
14	4		*FRONT BUMPER LOCKING CLIP	Not Necessary	18.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	198.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,043.00 FS	*- FS
17	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	86.00 FS	*- FS
18	2		*HORN -LH/RH	Not Necessary	416.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR -INNER (NPA)	Not Necessary	0.00 FS	*- FS
20	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR -OUTER (NPA)	Not Necessary	0.00 FS	*- FS
22	2		*HEADLIGHT MOUNTING -LH/RH	Necessary	264.00 FS	*105.20 FS
23	2		*HEADLIGHT -LH/RH	Not Necessary	17,416.00 FS	*- FS
24	2		*LIFT CYLINDER -LH/RH	Not Necessary	306.00 FS	*- FS
25	1		*LIFT CYLINDER HOSE	Not Necessary	145.00 FS	*- FS
26	2		*FRONT FENDER -LH/RH	Not Necessary	2,924.00 FS	*- FS
27	2		*FRONT FENDER BRACE -LH/RH	Not Necessary	500.00 FS	*- FS
28	2		*FRONT FENDER BRACKET -LH/RH	Not Necessary	40.00 FS	*- FS
29	2		*S-LINE EMBLEM	Not Necessary	266.00 FS	*- FS
30	2		*FRONT WHEEL HOUSING LINER -LH/RH	Not Necessary	606.00 FS	*- FS
31	2		*FRONT WHEEL SPOILER -LH/RH	Not Necessary	353.00 FS	*- FS
32	2		*FRONT WHEEL ARCH COVER -LH/RH	Necessary	1,418.00 FS	*1,134.40 FS
33	1		*FRONT BUMPER TOP COVER	Not Necessary	144.00 FS	*- FS
34	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
35	1		*AIR COND STICKER	Not Necessary	22.00 FS	*- FS
36	1		*FRONT NO PLATE	Cut	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Necessary	350.00 FS	*38.96 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 38,043.00 4,594.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,BOTH FRONT FENDER AND BOTH HEADLIGHTS ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	3,200.00	600.00
4	TO RESPRAY FRONT BUMPER ,FRONT BUMPER LOWER SPOILER ,BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS	New	5,000.00	1,000.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,672.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >