

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

### **ESTIMATE**

| Invoice Name & Address   | Owner Name & Vehicle Info |  |  |  |  |
|--------------------------|---------------------------|--|--|--|--|
| LONPAC INSURANCE BHD     | Cust No/Name              | LCV15096/Mr Yeo Chee Tiong (yang Zhizhon |  |  |  |
| 300 BEACH ROAD #17-04/07 | Reg No/Reg Date           | SLF1459E*#F / 16/08/2016                 |  |  |  |
| THE CONCOURSE            | Date In/Mileage           | 23/05/2022/ 112939                       |  |  |  |
| SINGAPORE 199555         | Chassis No                | KNAFZ411MH5649029                        |  |  |  |
| TEL:62962706             | Engine No                 | G4FGGH638093                             |  |  |  |
| Contact No               | Make/Model                | KIA/FORTE K3 1.6 A SX HADQ               |  |  |  |
|                          | Colour/Trim               | B4U / WK                                 |  |  |  |

| count No  | Terms   | Date/Tim   | ne Printed   | CSE  | Operate  | or   |  | WIP No  |                                 |                                 |                                 |
|-----------|---|--|--|--|--|--|--|---|---------------------------------|---------------------------------|---------------------------------|
| 000040    | Credit  | 23/05/20   | 022/ 15:30   | DS   | 303 / 1  | Renemer  |  | 30145   |                                 |                                 |                                 |
|           |   | Descrip  | tion of Good   | s / Services   |  |  | Qty  |   |                                 |                                 | mount                           |
| MIPNT8808 | 38  |  |  |  |  |  | 11.  | c 1 M   | - /                             | 1                               | 250.00                          |
|           |   | IING   |  |  |  |  | 100  | mon   | m                               |                                 | -                               |
|           |   |  |  |  |  |  |  | de  |                                 |                                 | 100.00                          |
|           |   | HTING/WIR  | ING SYSTEM   | ON REAR AC   | CIDENT AF  | FECTED ARE   | AS   | 1 11,   | 1                               |                                 | 17000                           |
|           |   |  |  |  |  |  | Cer  | uprise  | 2001 P                          | edy.                            | 640.00                          |
|           |   |  |  |  | FACILITA   | IE   | c-1  | 27/8  | 122                             | /                               |                                 |
|           |   | ACCIDENT A   | FFECTED ARE  | AS   |  |  | 5 dys.   | 0 // 0/   | 101                             | 10                              | 200.00                          |
|           |   | VIT ON N   | EW & DEDATE  | DANELS   |  |  |  |   |                                 | " (                             | 200.00                          |
|           |   | KII ON N   | LW & KLFAIR  | TANLL'S  |  |  |  |   | 1600                            |                                 | 4480.00                         |
|           |   | FMRI FMS II  | PR & I WR RE   | AR RIMPER  | CTITPS BRA   | CKETS  | 640  | C   | 000                             |                                 |                                 |
|           |   |  |  |  |  |  | 125  |   |                                 |                                 |                                 |
|           |   |  |  |  |  | R FENDER   | 17110  |   |                                 |                                 |                                 |
|           |   |  |  |  |  |  | +140   | 7   |                                 |                                 |                                 |
|           |   |  | - Investment -   |  | hood hood foud   | Second Comments  |  | 2   | root                            |                                 | 2750.00                         |
| SPRAY PA  | INTING O  | N REAR AC  | CIDENT AFFE  | CTED AREAS   | ; F.   | SU   |  |   |                                 |                                 |                                 |
| MIPNT880  | 38  |  |  |  |  |  |  |   | 11                              | X                               | 50.00                           |
| REAR LICE | ENSE PLA  | ATE WITH F   | RAME   |  |  |  |  |   |                                 |                                 |                                 |
|           |   |  |  |  |  |  |  | nu  | 30                              | -                               | 50.00                           |
|           |   |  |  |  |  |  |  |   |                                 | -                               | 44.00                           |
|           |   |  |  |  |  |  |  |   |                                 |                                 | 44.00                           |
|           | A7 030  |  |  |  |  |  |  |   |                                 |                                 | 42.00                           |
|           | 10  |  |  |  | en   |  |  |   |                                 |                                 | 40.00                           |
|           |   |  |  |  |  |  |  |   |                                 |                                 | 688.00                          |
|           |   |  |  |  |  |  |  |   |                                 | -                               | 315.00                          |
|           |   |  |  |  |  |  |  |   |                                 | _                               | 29.00                           |
|           |   |  |  |  |  |  |  |   |                                 | X                               | 29.00                           |
|           |   |  |  |  |  |  |  |   |                                 | -                               | 20.00                           |
|           |   |  |  |  |  |  |  |   |                                 | 18/                             | 708.00                          |
|           |   |  |  |  | 11   |  | 1.00   | 42.00   | 0.00                            | 8                               | 42.00                           |
|           |   |  |  |  | 11   |  | 2.00   | 6.00  |                                 | à.                              | 12.00                           |
|           |   |  |  |  | 11   | ¥  | 1.00   | 6.00  | 0.00                            | 8                               | 6.00                            |
|           | MIPNT8808 DIAGNOSTI MIPNT8808 TO CHECK MIPNT8808 TO REMOVE REPAIR ON MIPNT8808 TO APPLY MIPNT8808 TO REPLAC SENSORS, UTO CUT & STRAIGHTE MIPNT9808 SPRAY PAI MIPNT8808 REAR LICE MIPNT8808 C & C LOC KS 86310 KS 86311 WFFORTE WFEMBLEMI KS 86611 KS 86613 KS 86614 KS 0G032 KS 95720 KS 86690 KS 86636 | MIPNT88088 DIAGNOSTIC/SCANN MIPNT88088 TO CHECK ALL LIG MIPNT88088 TO REMOVE & RE-I REPAIR ON REAR A MIPNT88088 TO APPLY SEALANT MIPNT88088 TO REPLACE LOGO, SENSORS, UNDER CO TO CUT & WELD RE STRAIGHTEN, REFORMIPNT98088 SPRAY PAINTING OMIPNT88088 REAR LICENSE PLA MIPNT88088 REAR LICENSE PLA MIPNT88088 C & C LOGO KS 86310 A7 050 KS 86311 A7 030 WFFORTE WFEMBLEMK3 KS 86611 A7 810 KS 86695 A7 810 KS 86613 A7 001 KS 86614 A7 001 | Descrip MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIR MIPNT88088 TO REMOVE & RE-INSTALL AL REPAIR ON REAR ACCIDENT A MIPNT88088 TO APPLY SEALANT KIT ON N MIPNT88088 TO REPLACE LOGO, EMBLEMS, U SENSORS, UNDER COVER, REINF TO CUT & WELD REAR END PA STRAIGHTEN, REFORM, ALIGN O MIPNT98088 SPRAY PAINTING ON REAR AC MIPNT88088 REAR LICENSE PLATE WITH F MIPNT88088 C & C LOGO KS 86310 A7 050 KS 86311 A7 030 WFFORTE WFEMBLEMK3 KS 86611 A7 810 KS 86613 A7 001 KS 86613 A7 001 KS 86614 A7 001 KS 86614 A7 001 KS 95720 A7 0009 P KS 86690 A7 000 KS 86636 A7 000 | Description of Good MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/T REPAIR ON REAR ACCIDENT AFFECTED ARE MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR MIPNT88088 TO REPLACE LOGO, EMBLEMS, UPR & LWR RE SENSORS, UNDER COVER, REINFORCEMENT, AN TO CUT & WELD REAR END PANEL -TO RE STRAIGHTEN, REFORM, ALIGN ON REAR ACCI MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFE MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-K KS 86311 A7 030 EMBLEM-CERA WFFORTE FORTE EMBLE WFEMBLEMK3 EMBLEM K3 KS 86611 A7 810 UPR COVER-F KS 86695 A7 810 CTR COVER-F KS 86613 A7 001 LH SIDE BRA KS 86614 A7 001 RH SIDE BRA KS 95720 A7 0009 P ULTRASONIC KS 86690 A7 000 LH UNDER CO | Description of Goods / Services  MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACMIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO REPAIR ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS MIPNT88088 TO REPLACE LOGO, EMBLEMS, UPR & LWR REAR BUMPER, SENSORS, UNDER COVER, REINFORCEMENT, ANTENNA, STAY TO CUT & WELD REAR END PANEL | DOOO040 Credit 23/05/2022/ 15:30 DS 303 / IDESCRIPTION OF GOODS / Services  MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFINENSE REPAIR ON REAR ACCIDENT AFFICTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITA REPAIR ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS MIPNT88088 TO REPLACE LOGO, EMBLEMS, UPR & LWRIREAR BUMPER, CLIPS, BRASENSORS, UNDER COVER, REINFORGEMENT, ANTENNA, STAYS, ETC. TO CUT & WELD REAR END PANEL TO REPAIR REAR BOOT & LHSTRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB ALL MIPNT88088 C & C LOGO KS 86311 A7 030 EMBLEM-CERATO ALL MIPNT88088 C & C LOGO KS 86311 A7 030 EMBLEM-CERATO ALL MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB ALL MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB ALL MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB ALL MIPNT88088 C & C LOGO KS 86631 A7 001 LH SIDE BRACKET-REAR BUMPE ALL MIPNT8808 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNT88088 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNT88088 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNT88088 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNT88088 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNT88088 C & C LOGO CTR COVER-REAR BUMPE ALL MIPNTS COVER-REAR BUMP | Description of Goods / Services  MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED ARE MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS MIPNT88088 TO REPLACE LOGO, EMBLEMS, UPR & LWRIREAR BUMPER, CLIPS, BRACKETS, SENSORS, UNDER COVER, REINFORCEMENT, ANTENNA 15 TAYS, ETC TO CUT & WELD REAR END PANEL TO REPAIR REAR BOOT & LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86311 A7 030 EMBLEM-CERRATO MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86310 A7 000 LOGO ASSY-KIA SUB MIPNT88088 C & C LOGO KS 86611 A7 810 UPR COVER-REAR BUMPE MIPNT88088 C & C LOGO KS 86613 A7 001 LH SIDE BRACKET-REAR MIPNT8808 KS 86614 A7 001 RH SIDE BRACKET-REAR MIPNT8808 KS 86614 A7 001 RH SIDE BRACKET-REAR BUMPE MIPT MIPNT8808 KS 86690 A7 000 LH UNDER COVER-RE BP MIPNT8808 KS 86690 A7 000 LH UNDER COVER-RE BP MIPNT88086 KS 86636 A7 000 LH UNDER COVER-RE BP MIPT MIPTS MI | Description of Goods / Services  Description of Goods / Services  MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS MIPNT88088 TO REPLACE LOGO, EMBLEMS, UPR & LWRIREAR BUMPER, CLIPS, BRACKETS, SENSORS, UNDER COVER, REINFORGEMENI, ANTENNA, STAYS, ETC CUT & WELD REAR END PANEL TO REPAIR, REAR BOOT & LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 C & C LOGO KS 86310 A7 050 LOGO ASSY-KIA SUB MIFORTE FORTE EMBLEM MIPNT88088 C & C LOGO WFFORTE FORTE EMBLEM MIPNT88088 C & C LOGO KS 86311 A7 030 EMBLEM-CERATO UPR COVER-REAR BUMPE  1.00 WFFORTE FORTE EMBLEM MIPNT88088 C & S LOGO LH SIDE BRACKET-REAR MIPNT88088 C & C LOGO KS 86613 A7 001 LH SIDE BRACKET-REAR MIPNT88088 C & C LOGO LH UNDER COVER-RE BP 11 LOO KS 86613 A7 001 LH SIDE BRACKET-REAR MIPNTS LH SIDE BRACKET-REAR LH LOO MISS 86636 A7 000 LH UNDER COVER-RE BP 11 LOO MISS 86636 A7 000 LW BRACKET-REAR BEA | Description of Goods / Services | Description of Goods / Services | Description of Goods / Services |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

### **ESTIMATE**

| Invoice Name & Address   | Owner Name & Vehicle Info                       |                            |  |  |  |  |
|--------------------------|---|----------------------------|--|--|--|--|
| LONPAC INSURANCE BHD     | Cust No/Name LCV15096/Mr Yeo Chee Tiong (yang Z |                            |  |  |  |  |
| 300 BEACH ROAD #17-04/07 | Reg No/Reg Date                                 | SLF1459E*#F / 16/08/2016   |  |  |  |  |
| THE CONCOURSE            | Date In/Mileage                                 | 23/05/2022/ 112939         |  |  |  |  |
| SINGAPORE 199555         | Chassis No KNAFZ411MH5649029                    |                            |  |  |  |  |
| TEL:62962706             | Engine No                                       | G4FGGH638093               |  |  |  |  |
| Contact No               | Make/Model                                      | KIA/FORTE K3 1.6 A SX HADQ |  |  |  |  |
|                          | Colour/Trim                                     | B4U / WK                   |  |  |  |  |

| Account No   | Terms                                | Date/Time Printed  | CSE   | Operator                                  |             |   | WIP No  |                                      |        |   |
|--|--------------------------------------|--|---|---|-------------|---|---|--------------------------------------|--------|---|
| F0000040   | Credit                               | 23/05/2022/ 15:30  | DS  | 303 / Ren                                 | emer        |   | 30145   |                                      |        |   |
|  |                                      | Description of Good  | s / Services  |   |             | Qty                                       | Unit Price  | Disc%                                | -      | nount   |
| M KS 86631<br>M KS 95420<br>M KS 86633<br>M KS 86634<br>M KS 86641<br>M KS 86642 | A7 200<br>A7 800<br>A7 800<br>A7 800 | BEAM-REAR B<br>ANTENNA ASS<br>LH UPR BRAC<br>RH UPR BRAC<br>LH STAY-RR<br>RH STAY-RR   | Y-SMARTKE<br>KET-REAR<br>KET-REAR<br>BUMPER                               | SVC<br>11<br>11<br>11                     |             | 1.00<br>1.00<br>1.00<br>1.00<br>1.00      | 318.00<br>69.00<br>3.00<br>3.00<br>120.00<br>120.00 | 0.00<br>0.00<br>0.00<br>0.00<br>0.00 | X<br>X | 318.00<br>69.00<br>3.00<br>3.00<br>120.00<br>120.00 |
| M KS 85770<br>M KS 69100<br>Z NOTES<br>ACCIDENT<br>OWNER CL<br>REQUIRED          | A7 000W<br>A7 600                    | RR TRIM-TRA<br>PANEL ASSY-<br>5/022 ALONG UPPER SE<br>HIRD PARTY<br>MENT CAR   | NSVERSE<br>BACK<br>RANGOON SL   | IP RD TO HOL                              |             |   | 58.00<br>324.00                                     |                                      | ×      | 58.00<br>324.00                                     |
|  |                                      |  |   |   |             |   |   |                                      | No.    |   |
|  |                                      |  |   |   |             |   |   |                                      |        |   |
|  |                                      | LKK Auto Consult the Repairer of th To resurvey before. To display damaged Parts prices are sul Third party survey.  | after spray painting part(s) during rebiject to confirmation a "Without F | ng<br>esurvey<br>tion<br>Prejudice" basis |             |   |   |                                      |        |   |
|  |                                      | <ul> <li>Third party survey</li> <li>No illegal modification</li> <li>Supplementary ite is subject to final at a subject to final at</li></ul> | tion(s) is an   | ing boyen                                 |             |   |   |                                      |        |   |
|  |                                      | Acknowledged by F Signature: Date:   |   |   |             |   |   |                                      |        |   |
| Confirm &  | accepted l                           | And the second s           |   |   | L<br>S<br>S | Parts Labour Standard Specialis Others(Lu | t Job   | Survey, a                            |        | 3,005.0<br>0.0<br>0.0<br>8,520.0<br>0.0<br>0.0      |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

SUPP.

### **ESTIMATE**

| Invoice Name & Address   | Owner Name & Vehicle Info  |  |  |  |  |
|--------------------------|--|--|--|--|--|
| LONPAC INSURANCE BHD     | Cust No/Name   | LCV15096/Mr Yeo Chee Tiong (yang Zhizhon   |  |  |  |
| 300 BEACH ROAD #17-04/07 | Reg No/Reg Date  | The state of the s |  |  |  |
| THE CONCOURSE            | Date In/Mileage 23/05/2022/ 112939<br>Chassis No KNAFZ411MH5649029 |  |  |  |  |
| SINGAPORE 199555         |  |  |  |  |  |
| TEL:62962706             | Engine No  | G4FGGH638093   |  |  |  |
| Contact No               | Make/Model   | KIA/FORTE K3 1.6 A SX HADQ   |  |  |  |
|                          | Colour/Trim  | B4U / WK   |  |  |  |

| Account No                        | Terms  | Date/Time Printed   | CSE          | Operator      |      | WIP No     |       |        |
|-----------------------------------|--------|---------------------|--------------|---------------|------|------------|-------|--------|
| F0000040                          | Credit | 27/05/2022/ 10:50   | DS           | 303 / Renemer |      | 30145      |       |        |
|                                   |        | Description of Good | s / Services |               | Qty  | Unit Price | Disc% | Amount |
| M KS 92401                        | A7 700 | LH OTR LAMP         | ASSY-REA     | CNe           | 1.00 | 788.00     | 0.00  | 788.00 |
| M KS 92403<br>Z NOTES<br>SUPPLEME |        | LH INR LAMP         | ASSY-REA     | CN.           | 1.00 | 710.00     | 0.00  | 710.00 |

Estimate

| 0.51                                   | Parts            | 1,498.00      |
|--|------------------|---------------|
| Confirm & accepted by                  | Labour           | 0.00          |
|  | Standard Menu    | 0.00          |
|  | Specialist Job   | 0.00          |
|  | Others(Lub, etc) | 0.00          |
|  | Sundry           | 0.00          |
|  | Total (w/o GST)  | 1,498.00      |
| Authorized signatory and company stamp |                  | 2015年第二届新华·英州 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1