



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9840C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	502.46	502.46
1	FENDER WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	89.44	-
1	DOOR MIRROR LH (CONSISTENT)	CRACKED	950.90	950.90
1	DOOR PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,823.50	-
1	DOOR SEAL FRT LH (CONSISTENT)	SERVICEABLE	46.68	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	175.96	-
1	DOOR HINGE LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	192.66	-
1	DOOR CHECK FRT LH (CONSISTENT)	SERVICEABLE	124.86	-
1	DOOR LOCK FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	582.53	-
1	DOOR CATCH FRT LH (CONSISTENT)	SERVICEABLE	84.12	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	SERVICEABLE	165.46	-
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	8.48	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	85.64	-
1	ROCKER PANEL OUTER LH (CONSISTENT)	SERVICEABLE	633.01	-
	LESS 10% DISCOUNT		-546.57	-145.34
			4,919.13	1,308.02
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET WHEELARCH CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			242.00	90.00
<b><u>LABOUR</u></b>				
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER AND DOOR LOCK FRT LH.		2,800.00	400.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
			6,700.00	950.00
<b>GRAND TOTAL</b>			<b>11,861.13</b>	<b>2,348.02</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,348.02</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/AXA15003333/Kja3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.